

GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF THE REGIONAL CONTROLLER OF MINES



Tel No.080 23371027 Fax No.080 23373287

Email ID: ro.bangalore@ibm.gov.in, rcombng@rediffmail.com

29, Industrial Suburb, II Stage Tumkur Road, Goruguntapalya Yeshwantpur, Bangalore-560022

No. KNT/BLR/Fe/331/BNG/Vol-VIIDated: 28/9/ 2015 To, The Executive Director M/s National Mineral Development CorporationFax- 08395-274687 Donimalai Iron Ore Mines Bellary District, Karnataka.

Subject:- Violation of provisions of MCDR 1988 in respect of Donimalai Iron Ore Mine (ML No. 2396) over an extent of 597.54 ha inSandurTaluk&Bellary District, Karnataka State...Reg. Sir,

The following provisions of Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 2/7/2015 by Shri. V.J.K. Babu, RCOM (SZ), IBM, Bengaluru in the presence of Mines Manager ShriS.K. Jain & Geologist Shri. D.N. Shiyashankarappa.

bengaluru	in the presence of Mines Manager ShriS.K. Jain & Geologist Shri. D.N. Shivashankarappa.
Rule	The Modified Scheme of Mining was approved vide letter No. KNT/BLR/MS/Fe-178-
13(1)	SZdated 17/2/2014 for the period from 2013-14 to 2016-17. The deviations observed in
	mining operations vis-a-vis approved document are given below:
	(i) It was proposed to drill 24 bore holes in 3E, 3W & SB deposits, during the year 2014-15, but drilled only 2 bore holes in 3W deposits. Similarly, it was proposed to drill 27 bore holes in 2W & BMMX deposits, against which 18 bore holes in 3W & SB deposits up to 31/6/2015, and deviated from the proposals.
	(ii). As per the condition No. (xii) of the approved document, the 4 seasons data every year on environmental monitoring has to be carried out but such report for the 1st quarter of 2015-16 has not been carried out so for. The data so generated should be maintained in a bound paged register kept for the purpose.
Rule 21	The machinery / equipment wise log book is not maintained as per the rule. (Each
	machine showing date-wise account of hours worked, hours not worked, reasons for
	non-working, consumption of fuel/energy and lubricants and output of the machine
	during the corresponding working hours. The summary of operation of each machine
	shall be recorded in the Log Book at the end of each month bringing out the percentage
	availability and percentage utilization of the machine, average hourly performance and
	average fuel/energy consumption per hour. Each page of the Log Book shall be
	numbered and the summary shall be signed and dated by the Mining Engineer).
Rule	Every owner, agent, manager or mining engineer shall submit a yearly report to the
23(E)(2)	Regional Controller of Mines, IBM before 1st July of every year setting forth the extent
	of protective and rehabilitative works carried out as envisaged in the approved mine
	closure plan, and if there is any deviation, reasons thereof. It was noticed that the said
D 1, 20	report pertaining to the year 2014-15, has not submitted so far.
Rule 29	The updated copies of plans & sections as per Rule 28 are to be submitted to Regional
	Controller of Mines on or before 30th June every year, the same has not been submitted.

Rule 46	Appointment of change of agent has not been submitted in Form –I to IBM.
Rule 48	The particulars of boreholes drilled have not been maintained in a bound page register
	as per Form-K.

- 02. In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.
- 03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-(C. Parameshwaran) Dy. Controller of Mines

Copy for kind information to:

- 1. The Controller of Mines (SZ), IBM, Bangalore.
- 2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, KhanijBhavan, Race Course Road, Bangalore 560 001.

Yours faithfully,

Sd/-(C. Parameshwaran) Dy. Controller of Mines