



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्ड नेहरू कॉलोनी, देहरादून (उत्तराखण्ड) 248001 / 100 Old Nehru Colony, Dehradun

(U.K.)248001

TEL- 0135-2678350 / 2671896, E-mail - ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST-16-DDN-CV-WFH Mine Code: 38HPR10019

दिनांक, 15-06-2020

सेवा में To: M/S Gupta Associates  
Village & Post -Dadahu,  
Tehsil.- Renukaji,  
Distt.- Sirmour,  
Himachal Pradesh-173022

E-mail: guptaassociates009@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Himalaya Limestone Mine, Mining Lease over an area of 15.55 ha located near Village: Mandoli, Tehsil: Renukaji, District-Sirmour, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the MCDR inspection made by the undersigned on 17.03.2020 in the presence of Shri D.K Sinha Mines Manager.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operations were not carried out in accordance with the approved modified mining plan vide letter no. 614(2)/MP-B-278/08-DDN dated 05.03.2019 to the following extent: 1) As per proposal during the year 2019-20, it was proposed to carry out 03 boreholes of total meterage 60, but during the inspection it was observed that no borehole has been carried out so far.
29(1)	The holder of a mining lease shall send to the authorized officer, intimation in Form C of the Schedule of reopening of a mine after temporary discontinuance, so as to reach them within fifteen days from the date of such reopening. However, the same has not been received till date.
33	The holder of a mining lease shall, on or before the 30 <sup>th</sup> day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rule for the year 2018-19

- In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- Mining operations can be suspended as per rule 11(2) in case of non compliance of rule 11(1).
- You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

डी. पी शर्मा /D. P. Sharma

सहायक खान नियंत्रक /Assistant Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनायें प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- निदेशक उद्योग निदेशालय, हि० प्र० सरकार, उद्योग भवन, शिमला (हि० प्र०). (geologicalwing@gmail.com)
- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines