



भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो,  
क्षेत्रीय खान नियंत्रक कार्यालय  
द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,  
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)  
फोन एवं फैक्स-0771-2282530, 2285590 ई-मेल: ro.raipur.ibm@gmail.com



क्र०- छग० / दुर्ग / चूप.-16 / रायपुर

खान कोड: 38 छ.ग. 01008

दिनांक :-11.07.2017

प्रति,

श्री प्रदीप गोयल, पट्टेदार  
गीदम रोड, नयापाड़ा,  
पोस्ट- जगदलपुर,  
जिला- बस्तर (छ.ग.)-494001

विषय:-

छत्तीसगढ़ राज्य के दुर्ग जिले में स्थित आपकी छापरभानपुरी चूनापत्थर खदान 1.53 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में।

महोदय,

आपकी उपरोक्त खान का निरीक्षण दिनांक 28.06.2017 को अधोहस्ताक्षरी द्वारा श्री प्रदीप गोयल, खान मालिक एवं श्री ए०के० जॉन, क्यू०पी० की उपस्थिति में किया गया तथा खान के निरीक्षण में पाया कि आपने खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबंधों का उल्लंघन किया है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
<b>Rule 11 (1)</b>	The following deviations have been found in the mine from approved Scheme of Mining Plan vide letter no. BST/LST/MPLN-722/NGP Dated 26/03/2013 for the period of 2012-13 to 2016-17: <b>Boundary Pillars:</b> It has been found that all the pillars does not have their serial/identification numbers. Boundary Pillars are not been constructed and maintained as per specification mentioned in MCR, 2016. <b>Borehole:</b> For the year 2013-14, it has been proposed to carry out 01 nos of borehole up to a depth of 30m, none of the borehole have been drilled <b>Development:</b> (i) No such proposal has been given in the earlier approved MP/MMP/SOM for mining at 7.5 m barrier zone. Development and excavation was observed all along the lease boundary, and most of places 7.5m barrier zone has been mined out. (ii) There was a proposal given for reduction of bench height up to 3 meters each with proper face slop whereas quarry has been developed and mined out up to a depth of 15-20 m without any proper benching. <b>Afforestation:</b> There was a proposal given for plantation of 125 nos of plants (25 nos. of plant every year) during 2012-13 to 2016-17. None of the plants have been planted.
<b>Rule 26 (2)</b>	A yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out has not been submitted for the year 2015-16 and 2016-17.
<b>Rule 27 (2)</b>	An amount equal to the difference between the financial assurance due has not been submitted within ninety days from the date of notification.
<b>Rule 33</b>	Updated print copy of the surface geological plan and sections has not been submitted before 30th day of June for the year 2015-16 and 2016-17.
<b>Rule 35</b>	Online self assessment report of mining and allied activities as per the notified template of star rating in the format prescribed by the Indian Bureau of Mines before 1st day of July for the year 2016-17 has not been submitted.
<b>Rule 45 (7)</b>	Annual Returns of 2016-17 has been scrutinized and it has been found that the Consignee name and registration no. as allotted by IBM to the buyer, have not been mentioned in the return.
<b>Rule 54</b>	Labour attendance register & production register have not been maintained.
<b>Rule 55</b>	Part time Mining Engineer and a Geologist are not been appointed.

Continue...2..

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं इस नियम का उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवं 45(7)(क) के अंतर्गत

(क) खान की समस्त खनन संक्रियाएं बंद की जा सकती है।

(ख) आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है।

(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।

03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पर के पारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(शैवाल कार्तिकेय)  
कनिष्ठ खनन भूविज्ञानी,  
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि: सूचनार्थ हेतु :-

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर-440001
2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़।

(शैवाल कार्तिकेय)  
कनिष्ठ खनन भूविज्ञानी,  
भारतीय खान ब्यूरो, रायपुर