

## Government of India Ministry of Mines Indian Bureau of Mines Office of the Regoinal Controller of Mines, Jabalpur

File No. MP/BGT/Manganese/RMP-46/19-20 807 - 811

Date: 09/04/2020

To,

Sh. D Shome, Nominated Owner & Director (Production & Planning) M/s MOIL Limited MOIL Bhawan, 1-A, Katol Road Nagpur-440013 (Maharastra)

To,

Mine Manager, Sitapatore Mn Mine (4.73 Ha), M/s MOIL Limited Village –Sitapatore, Tehsil - Tirodi Dist- Balaghat (MP)

**Subject:** Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Inspection of Sitapatore Mn Mine (Area- 4.73 Ha), M/s MOIL Limited.

Sir,

Undersigned has inspected your mine in the presence of Sh M. K. Singh (Mine Manager), Sh M.R. Bhanse, (Mine Geologist), Sh Anil Rajput (Mine Geologist) and Sh Subhransu Pani (Mine Geologist) on 08/02/2020. Following provisions of MCDR 2017 were found violated in your mines during inspection.

## Rule No

## Nature of violation observed in detail

Rule 11(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.

The document of above mentioned mine was approved vide letter No.-MP/BGT/Mangnese/RMP-63/17-18 dated 19/09/2017.

During inspection it has been observed that the following provisions of the rule have been violated:-

- a) It was proposed to remove 4250 m3 quantity of OB from pit no-06. But, it was observed during inspection that no OB has been removed from pit no-06 for development of mine in the year 2018-19. The mine development was lagging from the proposal and not as per the approved proposals.
- Rule 26(2) The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1<sup>st</sup> day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof:

  During scrutiny of the office records, it has been observed that the yearly report in respect of rule 26(2) of MCDR 2017 has not been submitted for the year 2018-19.
- Rule 33 Copies of plans and sections to be submitted The holder of mining lease shall on or before the 30th day of the June every year submit to the authorized officer, as the case may be, and the

State Govt. a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32.

During scrutiny of office records, it has been orbserved that no such copies plans and sections have been submitted by lessee at this office.

Rule 55 (1) For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules, -

a. every holder of reconnaissance permit shall employ a whole-time geologist;

b. every holder of prospecting licence or a prospecting license-cum-mining lease shall employ

a whole-time geologist and a part-time mining engineer;

c. every holder of a mining lease shall employ, in case ofcategory 'A' mines, a whole-time mining engineer and a geologist;

category 'B' mines, a part-time mining engineer and a part-time geologist:

Provided that in the case of fully mechanised category 'A' mines, the mining engineers and geologists shall have minimum five years of professional experience of working in a supervisory capacity in the field of mining.

During the scrutiny of office records, it has been observed that appointment letter of whole time Mining Engineer and Mine Geologist have not been submitted for this lease area in the prescribed format as per provisions of rule.

- 1. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
- 3. You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भारतीय खान ब्यरो

## NOO:

प्रतिलिपि प्रेषित : :

01. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal(M.P.) for information and further necessary action.

02. The District Collector, Balaghat (M.P.) for information.

भारतीय खान ब्यूरो

प्रतिलिपि प्रेषित :

खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर को सूचनार्थ प्रेषित।

भारतीय खान

