



GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES

FAX : 080- 23371027 / 23373287  
Tel : 080-23371027 / 23375366 / 67  
Email ID: ro.bangalore@ibm.gov.in  
[rcombng@rediffmail.com](mailto:rcombng@rediffmail.com)

No.KNT/GLB/Lst-19/BNG/Vol.II

**BY SPEED POST**



29, Industrial Suburb, II Stage,  
Tumkur Road, Gorguntapalya,  
Yeshwantpur,  
Bangalore- 560 022.

Dated: 03.04//10/2013

To,

Sri. Rajesh Garg,  
Vice President( Mines),  
M/s. Vasavadatta Cement,  
SEDAM – 585 222  
Dist., Gulberga (Karnataka).

Subject : Violation of provisions of MCDR 1988 in respect of Injepalli Limestone Mine ( ML No.2417) over an extent of 897.86 Ha. n/v Sedam, Taluk – Sedam and Dist., Gulberga Karnataka State....reg.

Sir,

The following provisions of Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 23.09.2013 by the undersigned in the presence of yourself and Mr. Ravindra Lagwankar – Mines Manager.

Rule No.	Nature of violation observed
13(1)	During 2012-13, production of limestone 4.36 Lac. Mt. only was raised against proposals of 9.25 Lac Mt, which is only 47.14%. For last five years i.e., 2008-09 to 2012-13, it was 25.49 Lac Mt. only against the proposals of 49.78 Lac Mt. which is 51.20%.
48	Records of prospecting bore holes drilled are not maintained in Form – K.

02 In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operation till the compliance of the violations.

03. You are, advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

04. It is also noticed that Boundary pillars does not bear correct co-ordinates and requisite details and direction, as per the specifications prescribed vide CCOM's Circular No. 1/2009 dated 03.09.2009. You are advised to erect the same and furnish the photographs along with co-ordinates within 30 (Thirty ) days from the date of issue of this letter.

Yours faithfully,

( PUKHRAJ NENIVAL)  
Dy. Controller of Mines.

Copy for kind information to :-

1. The Controller of Mines(SZ), Indian Bureau of Mines, Bangalore – 22.

( PUKHRAJ NENIVAL)  
Dy. Controller of Mines.