VIOLATION LETTER REGD/AD

Dated %04.06.2013

Hkkjr I jdkj [kku eæky; Hkkjrh; [kku C; jjks {ks=h; [kku fu; æd dk dk; kly; ibmbbsr@dataone.in



Government of India Ministry of Mines Indian Bureau of Mines Office of the Regional Controller of Mines.

| File No. ORI/IRON/KJR/MCDR-27/BBS | Mahani Complex, 2 nd Floor |
|-----------------------------------|--|
| | 308, District Centre, Chandrasekharpur |
| | Bhubaneswar-751 016 |
| | Ph-(0674)2742463 / Fax-0674 2744430 |

To, Shri Bibani Prasad Mohanty, Partner M/s Kalinga Mining Corporation. Jaruri Iron Ore Mines Samanta Niwas, Shaik Bazar Po/Dist– Cuttack, Odisha 752052

Sub: Violation of provisions of MCDR, 1988 in respect of Joruri Iron ore Mine (27.1705 Ha) of M/s KMC., in Keonjhar District of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 03.05.2013 by the undersigned along with Shri Ajay Kumar Pradhan, Sr. Inspector of Mines, Joda (Directorate of Mines, Odisha) and accompanied by S/Shri Smruti Ranjan Behera, Mines Manager and D Manoharan, Geologist of your mine.

| Rule No. | Nature of Violation | |
|-----------------------|---|--|
| Rule 12(2)& (3) | Scheme of mining approved vide this office letter dated is having proposals valid up to 31/03/2012. Presently the mine does not have valid proposals to carryout mining operations. The owner/agent/manager/mining engineer has not submitted scheme of mining 120 days before the expiry of earlier approved proposals | |
| Rule 27(4) | Plans and sections required as per the provision of rule 28 of MCDR 1988 have not been maintained updated within three months. Surface plan maintained at the site is not matching with actual field conditions in respect of quarry/ benches near ML pillar 'F'was observed. | |
| 33(2) | Retaining wall along bottom periphery of Sub grade stock is found damaged, thus not been maintained effectively to prevent escape off stocked material there from. | |

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.
- 03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

इब्राहिम शरीफ /(IBRAHIM SHARIEF) I qk; d [kku fu; ⊭d/ Assistant Controller of Mines

eny ifr ij ugh / Not on Original ifrfyfi fuEu dks l knj l poukFkl vxf"kr

- (1) [kku fu; a=d(e/; kppy)/The Controller of Mines (CZ), lkkjrh; [kku f; jjk@ Indian Bureau of Mines, ukxij /Nagpur-440 001.
- (2) Mk; jÐVj vkWD ekbUl /The Director of Mines,Mk; jÐVkýsV vkWD ekbUl @Directorate of Mines,mMH k l jdkj /Government of Orissa, gMl vkWD fMikVeV fcfYMx /Heads of Department Building, U; wdsi Vy /New Capital, lkpus oj /Bhubaneswar-751 001

(IBRAHIM SHARIEF)

I gk; d [kku fu; &d/ Assistant Controller of Mines
drs {ks=h; [kku fu; &d/For Regional Controller of Mines