

VIOLATION LETTER

REGD/ A D

Hkkjr ljdkj
[kku ea=ky;
Hkkjrh; [kku C;wjks
{ks=h; [kku fu;a=d dk
dk;kZy;
ibmbbsr@dataone.in



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.
Ph-(0674)2742463 / Fax-0674 2744430

| | |
|----------------------------------|--|
| File No. ORI/MN/SNG/MCDR- 3 /BBS | Mahani Complex, 2 nd Floor 308, District Centre, Chandrasekharpur Bhubaneswar-751 016 |
|----------------------------------|--|

To

Date : 17.07.2013

**Sri. M.D.Rustagi,
Nominated owner & Director
M/s Rungta Mines Ltd.
At/P.O. - Barbil
Dist: Keonjhar (Odisha)
PIN- 758 035**

Sub: Violation of provisions of MCDR, 1988 in respect of Kolmong Manganese Mine, M/s Rungta Mines Ltd. in Sundergarh District of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 22.06.2013 by the undersigned, accompanied by Sri. A. Sen, Sr.G.M. (Geology) & Randhir Kumar, Mining Engineer of your mine.

| Rule No. | Nature of Violation |
|----------|---|
| 13(1) | Mining operations have not been carried out in accordance with the Scheme of Mining approved on dated 08.06.2010 to the extent indicated below :- Ref. Para 6.5, page 6.3 of approved Scheme of Mining; Retaining wall and garland drain have not been constructed all around the toe of the waste dump-D2 near Quarry No. - 6 & 7 to prevent surface wash off and escape of material. |

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.

Besides, inability to comply the provision of Rule 13 (1) is also liable for suspension of mining operations according to Rule 13 (2) of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

(PREM PRAKASH)
Sr. Assistant Controller of Mines

ewy izfr ij ugh / Not on Original izfrfyfi fuEu dks lknj lwpukFkZ vxzsf"kr

- (1) [kku fu;a=d(e;/kazpy)/The Controller of Mines (CZ),Hkkjrh; [kku C;wjks@Indian Bureau of Mines, ukxiqj /Nagpur-440 001.
- (2) Mk;jsDVj vkWQ ekbUI /The Director of Mines,Mk;jsDVksjsV vkWQ ekbUI@Directorate of Mines,mM+hlk ljdkj /Government of Orissa, gsMI vkWQ fMikVZesaV fcfYMax /Heads of Department Building, U;w dSfiVy /New Capital, Hkqous'oj /Bhubaneswar-751 001.

(PREM PRAKASH)

Sr. Assistant Controller of Mines

d`rs {ks=h; [kku fu;a=d/For Regional Controller of Mines