

गुजरात राज्य में निकट ग्राम - खाम्बा, तालुका - सूत्रापाडा, जिला - गिर सोमनाथ
स्थित खाम्बा चूनापत्थर खान, सर्वे सं- १५०/पी, क्षेत्रफल- 4.6735 हे. के लिए
पट्टाधारी- सर्वश्री जी.एच.सी.एल. लि की खनिज संरक्षण एवं विकास नियमावली,
२०१७ के नियम २४ के अंतर्गत प्रस्तुत अंतिम खान बंद करने की योजना की जांच
पश्चात संवीक्षा टिप्पणी मय रिपोर्ट

- 1) Cover page: Date of lease execution is incorrect.
- 2) Introductory note: i. Lease period has extended up to 50 years. Information related to this has not been given.
ii. Information related to type of lease area (forest, non-forest etc), present land use pattern, and method of mining and mineral processing operations has not been given.
iii. Reasons for closure has not been properly given.
- 3) As per standard guideline/ format of Final mine closure plan points related to General, Location and accessibility and details of applied/lease area should be covered under introduction. KML file has not been enclosed.
- 4) Para 1.1: i. 'Uneconomic operations' should be added for closure reason.
ii. Proposal to develop mined out area should be discussed at closure plan (point 4.0).
- 5) Para 1.2: Information related to ministry of environment and forests, State or central pollution control board has not been given.
- 6) Para 1.3: i. Name of lessee/applicant has not been given.
ii. Copy of the resolution of the board of directors or any other appropriate administrative authority on the decision of closure of mine has not been submitted.
- 7) Para 2.1: At present there is no mound in the area. Topography of the area has not been properly described on page no. 5.
- 8) Para 2.2: Production of year 2017-18 has not been given.
ii. Balance reserves should be given clearly in table form. Reserves and resources have not been assessed correctly.
iii. Due to uneconomic and non-feasibility condition remaining 19,104 MT reserves should be categorized as 221 category.
- 9) Para 2.3: Extent of mechanization, mining machinery deployed, and production level has not been discussed.
- 10) Para 3: Reference of earlier approved MP/SOM has not been given. Review has also not been described properly on page no. 9 in respect of salient proposal of the mining plan. Information about the areas which might have been contaminated by mining activities has not been given.
- 11) Para 4.1: Originally the land was गौचर भूमि। Hence degraded land should be leveled and developed as गौचर भूमि।
ii. Proposal of two ramp one for entrance and other for exit of cow/other animals should be incorporated.
iii. Plantation should be proposed on periphery
iii. Proposed plantation, wire fencing etc should be given clearly in table form.
- 12) Para 4.7: i. Information about the future utilization of mine office has not been discussed.
ii. Electric service lines are present in the area.

- 13) Para 4.9: After mine abandonment plan period site will be opened for general public. So 'prohibited area and prevent entry of persons' should be omitted.
- 14) Para 6.0: i. Time scheduling should be given clearly (as July, 2018 to June, 2018). It should be segregated on activities basis.
ii. Bar chart showing time schedule for closure operations should be given.
- 15) Para 8.0: i. Area considered for financial assurance is different in 2nd (1.3283) and 3rd (1.0283) para.
ii. Calculation for financial assurance (by Rs. 2,00,000) should be given.
- 16) Para 9.0: An undertaking to the effect that all the measures proposed in this closure plan will be implemented in a time bound manner as proposed has not been given.
- 17) Some photographs of mined out pit should be annexed.
- 18) Feasibility report related to non-feasible mining condition should be submitted.
- 19) Survey NO is different on plate No 3, 4,5,6,7.
- 20) **Surface plan:** One boundary pillar has not been connected by three fixed point.