

भारत सरकार /Government of India

खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757

Fax No. : (0832) –2741758

E-Mail : ro.goa@ibm.gov.in

File No : KNT/BJP/Lst-93/Goa

Opp.Old R.T.O.'s Office,

P.O. FATORDA - 403602,

Margao-GOA

Date:-27.2.2018

Mine Code:-38KAR26073

To,

Sri Anil Sood, Nominated Owner,

South West Mining Ltd,

Near Talur Cross,

P.O, Vidyanagar-583275,

Toranagallu, Bellar.

Sub :-Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Muddapur Limestone and Dolomite Mine(M.L.No-2602) over an extent of 18.709 Ha. Situated in Muddapur village, Tq- Mudhol, in Bagalkot District of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on14/02/2018(F/N), by the undersigned in presence of Shri Murali Manas P, Mines Manager.

Rule	Nature of Violation observed
11(1)	<p>a) In the approved Scheme of mining dated 1/12/2014, there was a proposal to work between co-ordinates N-900 to 1110 and E-1050 to 1380 up to 542 RL in the year 2016-17 and between co-ordinates N-900 to 1110 and E-1050 to 1380 up to 530RL in the year 2017-18. During inspection it is observed that working has been not carriedout as per the proposal.</p> <p>b) In the approved document there is a proposal to dump waste between co-ordinates N-890 to N1010 and E-1500 to 1670. However dumping is made near working pit.</p> <p>c) In the approved document there was a proposal to drill total 14 boreholes in the year 2014-15 and 7 in 2015-16. However only 10 boreholes were drilled so far.</p> <p>d) Mineral stack is not made as per the proposal mentioned in the approved document dated 1.12.2014.</p> <p>e) After DGPS survey the lease area is reduced from 18.84Ha to 17.89Ha. Modification to approved document for the change in lease area after DGPS survey is not submitted so far.</p>
45(7)	<p>In the annual return submitted for the year 2016-17, sale value for the Bagalkot cement industries is shown as Rs 7564912 for 500 tons which is almost Rs, 15129.824/ ton and appears to be un-realistic.</p>

46	Notice of appointment of Mining Engineer Shri Murali Manas.P and notice of termination of previous Mining Engineer Shri Vinod Kumar is not sent to this office so far.
48	Details of drilled boreholes are not recorded in the form-I.

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(Kalmata.M.K)
Senior Mining Geologist
Indian Bureau of Mines

Copy forwarded to: -

1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
2. The Director, Directorate Mines and Geology, Govt.of Karnataka, Bengaluru.

(Kalmata.M.K)
Senior Mining Geologist
Indian Bureau of Mines