

भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय /MINISTRY OF MINES भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES

REGD AD/Mail/Fax

Phone: 0674-2352463; TeleFax: 0674-2352490; eMail:ro.bhubaneshwar@ibm.gov.in

> Plot No.149, Pokhariput In front of CPWD office, BHUBANESWAR-751020

Date: 21/07/2017

File No: ORI/IRON-MN/SNG/MCDR-16/BBS/VOL-II

√To,

Shri M.D. Rustagi, Nominated Owner M/s Bonai Industrial Company Ltd. Rungta Office, Main Road, Barbil-758 035 Dist. Keonjhar, Odisha.

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Teherai Iron & Manganese Mine in Sundargarh District of Odisha, over an extent of 137.46ha-Reg.

The following provisions of Mineral Conservation & Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above mine during inspection on 13.07.2017 by undersigned accompanied by Shri Abhijit Sen, AVP(Geology), Shri A.S. Mohapatra, AVP(Mining), Shri B.K Srivastava, Mines Manager & Shri K.K. Sha, Senior Inspector of Mines, O/o the Deputy Director of Mines, Koira.

Rule	Rule position	Status and extent of violation
	No holder of a mining lease shall	Mining operations have not been carried out in
	commence or carry out mining operations	accordance with the modification of scheme of
11(1)	in any area except in accordance with the	mining approved vide letter number MSM/FM/04-
	mining plan approved, modified or	ORI/BHU/2015-16, dated 21.07.2015. The extent
	reviewed by the Indian Bureau of	deviation is as given below:
	Minesor above the threshold value	Plantation for the year 2016-17 was proposed on
	limits declared under Schedule-A of the	the backfilling area of 2015-16 in Chattan Pit in
	Atomic Minerals Concession Rules, 2016.	between the gridlines N800-N1000 & E600-E750
		(DRG. No. 09) but no plantation has not been as
		per the proposal envisaged in the approved
		document for the said year.

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017. Besides, inability to comply the provisions of rule 11(1) also liable for suspension of mining operations under the provisions of rule 11(2) of MCDR, 2017.
 - 3. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

(G.C.SETHI)

Deputy Controller of Mines