

Violation letter
Regd/Speed Post

भारत सरकार /Government of India

खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757

Fax No. : (0832) –2741758

E-Mail : ro.goa@ibm.gov.in

File No:- GOA/Fe/146-VOL-VII

Opp.Old R.T.O.'s Office,

P.O. FATORDA - 403602,

Margao-GOA

Date:- 22.01.2018

To,

The Owner/Agent/Manager

Tolem De Quela(Keli) Iron ore Mine(TC No.41/1955)

M/s Salgaocar Mining Industries Pvt Ltd.

Salgaocar Bhavan ,Altinho,Panji,Goa,403001

Sub :Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Tolem De Quela(Keli) Iron ore Mine(TC No.41/1955), M/s Salgaocar Mining Industries Pvt Ltd, situated in Village – Pirna & Tivim, Bardez - Taluka, North Goa- District of Goa State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 10/01/2018 by the undersigned along with Shri Kalmata M.K., SMG, IBM Goa in presence of Mr. Subramany,Director and Mr.Gopalkrishna V.Gaonkar,Qualified Person.

Rule	Nature of Violation observed
11(1)	<p>Mining operations have not been carried out in accordance with the modification of Mining Plan approved vide MMP/MECH-66/GOA/2016-17 dated 04/01/2017.</p> <p>(i) As per the aforesaid approved Modification of Mining Plan, excavation were approved to be carried out by formation of regular shape of benches of height 7m and width more than the height.</p> <p>However during the inspection it was observed that benches were merged in irregular manner and width of the benches were not maintained as approved at places; and thus resulted the collapses of benches in the pit.This is against the systematic and scientific mining.</p> <p>(ii) It has been observed that the large quantity of washoff material from the top benches were accumulated at the bottom of the pit, which may lead the instability/failure of the mine pit strata due void of the upper benches.</p>
27(2)	<p>A financial assurance of an amount equal to the difference between the financial assurance due as on the date of notification of these rules and the financial assurance already furnished,shall be furnished to the authorized officer within a period of ninety days from the date of notification of these rule.</p> <p>However, the same has not been furnished to the competent authority under these rule.</p>

55(1)	<p>For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules:“Every holder of a mining lease shall employ, in case of category ‘A’ mines, a full time mining engineer and a full time Geologist”.</p> <p>However, during the inspection it was observed that a full time Mining Engineer has not been employed under this rule.</p>																									
45	<p>Part- VI, Para2. Production and Stocks of ROM ore at Mine-head(Iron Ore(Hematite)):-</p> <table border="1" data-bbox="328 562 1390 734"> <thead> <tr> <th>Year</th> <th>Category</th> <th>Opening Stock</th> <th>Production</th> <th>Closing Stock</th> </tr> </thead> <tbody> <tr> <td>2015-16</td> <td>a) Opencast workings</td> <td>177,744</td> <td>-</td> <td>177,744</td> </tr> <tr> <td>2015-16</td> <td>b) Dump Working</td> <td>4,637,541</td> <td>-</td> <td>4,637,541</td> </tr> <tr> <td>2016-17</td> <td>a) Opencast workings</td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td>2016-17</td> <td>b) Dump Working</td> <td>4,637,541</td> <td>0.00</td> <td>4,637,541</td> </tr> </tbody> </table> <p>From the above figures of annual returns it has revealed that, in the year 2015-16 , closing stock of ROM from opencast working was 177,744T whereas in the year 2016-17 returns it has indicated as nil. Further, large quantity of ROM opening/closing stock in the head of dump working was shown in the para.</p> <p>The above figures are unrealistic, incomplete or false as submitted by your mine lease.</p>	Year	Category	Opening Stock	Production	Closing Stock	2015-16	a) Opencast workings	177,744	-	177,744	2015-16	b) Dump Working	4,637,541	-	4,637,541	2016-17	a) Opencast workings	0.00	0.00	0.00	2016-17	b) Dump Working	4,637,541	0.00	4,637,541
Year	Category	Opening Stock	Production	Closing Stock																						
2015-16	a) Opencast workings	177,744	-	177,744																						
2015-16	b) Dump Working	4,637,541	-	4,637,541																						
2016-17	a) Opencast workings	0.00	0.00	0.00																						
2016-17	b) Dump Working	4,637,541	0.00	4,637,541																						

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines

Copy forwarded to: -

1. The Dy. Director General (Stat), IBM, Nagpur
2. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
3. The Director, Directorate Mines and Geology, Govt. of Goa, Panaji.

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines