

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-10A  
गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, Sector 10A,  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: [ro.gandhinagar@ibm.gov.in](mailto:ro.gandhinagar@ibm.gov.in)

फाइल संख्या/File No.: GUJ/Porb/Lst-224

Date: 04/08/2021

**Mine Code – 38GUJ08250**

प्रेषित/To: श्री देवा कारा भूटिया  
“ गतराल कृपा “ सत्यम पार्क, रजीवनगर  
जिला – पोरबंदर (गुजरात) – 360575  
E-mail- [devabhutiya@yahoo.co.in](mailto:devabhutiya@yahoo.co.in)

विषय /Subject: Violation notice of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Ranavav Limestone Mines, Sy. No.-78/5/P, over an area of 11.33 ha located near Village- Ranavav, Taluka-Ranavav, District-Porbandar in Gujarat.

महोदय / Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 26.06.2021 in the presence of Shri Deva Kara Bhutiya :

<b><u>Rule No.</u></b>	<b><u>Nature of violation observed</u></b>
11(1)	For the year 2020-21 there was proposal to plant 327 saplings in 7.5 m safety zone, which has not been done.
26(2)	The holder of mining lease has not submitted a yearly report for the Year 2020-21 for the extent of protective and rehabilitative work carried out.
33	Digital copy along with print copy of Surface Geological Plan as maintained under Rule 32 of MCDR 2017 has not been submitted to this office
34(1)	The digitally prepared updated plans & sections were not present during inspection. <i>(Rule 34(1) of MCDR 2017 should be read with Rule 31(4) of MCDR 2017, which clearly says Plans &amp; Sections required under these rules shall be maintained up to date within 3 months in case of category “A” mines.)</i>
55(1)(c)(i)	A whole time Geologist has not been appointed till the date of Inspection.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय /Yours faithfully,

नमन एक्का / Naman Ekka

वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

मूल प्रति में नहीं :-

फाइल संख्या/File No.: GUJ/Porb/Lst-224

Date: 04/08/2021

प्रतिलिपि सुचनार्थ हेतु /Copy for information to:

1. खान नियंत्रक (उ. आ.), भारतीय खान ब्यूरो, उदयपुर ।
2. आयुक्त, भूविज्ञान एवं खनन निदेशालय, गुजरात ।
3. जिला भू- वैज्ञानिक, खनिज एवं खनन विभाग, कलेक्टर ऑफिस बिल्डिंग, ग्राउंड फ्लोर, रानीबाघ, पोरबंदर ।
4. कार्यालय प्रतिलिपि ।

नमन एक्का / Naman Ekka

वरिष्ठ खनन भूविज्ञानी /Senior Mining Geologist