

भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो

क्षेत्रीय खान नियंत्रक का कार्यालय

कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-

10A गांधीनगर, गुजरात, 382010



Government of India

Ministry of Mines

Indian Bureau of Mines

Office of Regional Controller of Mines

Karmayogi Bhavan, 4th Floor, Block-2, Sector 10A,

Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई -मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाईल संख्या File No: GUJ/JMNG/LST-025

Mine Code: 38GUJ07008

दिनांक 11 Oct. 2021

सेवा में To : Owner/Agent/Manager/Mining Engineer

प्रेषित : M/s Shree Digvijay Cement Co Ltd.,

(anil.nigam@digvijaycement.com)

Digvijaygram, Village-Sikka,

District-Jamnagar,

Dwarka- Gujarat

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Chorbedi-2 Limestone Mine over an area of 20.23.41 ha located near Village-Chorbedi, Tehsil-Lalpur, District-Jamnagar in Gujarat.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 07.9.2021 AN in the presence of Sh. Sh. Anil Nigam, Lessee rep.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
26(1)	The holder of a mining lease shall have the responsibility to ensure that the protective measures including reclamation and rehabilitation works have been carried out in accordance with the approved mine closure plan or with such modifications as approved by the competent authority. <u>In your case, you have not carried out protective measures as proposed in FMCP & conditions made there under.</u> Further rate of survival of plantation is reported as 11% in AR-2020-21 which is not satisfactory & self-sustained.
33	The owner, agent, mining engineer or manager of mine shall submit the digital copy along with a print copy of the Surface Geological plan & section on or before the 30th June of every year. In your case, you have not submitted the aforesaid updated plan & section maintained under rule 32 of MCDR, 2017 to this office till date.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease, has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

(जी.राम/G.Ram)

वरिष्ठ सहायक खान नियंत्रक /Sr.Assistant Controller of Mines

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाई हेतु प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- आयुक्त, भूविज्ञान एवं खनन, निदेशालय, गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित। (cgm@gujarat.gov.in)
- 3- DDG, MMS Division, भारतीय खान ब्यूरो, नागपुर -requested for Refer back for above scrutiny & update.
- 4- MCDR/गाई फाइल

वरिष्ठ सहायक खान नियंत्रक /Sr Assistant Controller of Mines