

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-10A  
गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, Sector 10A,  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाइल संख्या File No: GUJ/Porb/Lst-106/1088 Mine Code: 38GUJ08026

दिनांक 4 August 2021

सेवा में To : M/s Nirma Limited, Lessee  
NIRMA House, Ashram Road,  
Near Income tax, Ahmadabad,  
Gujarat-380009.  
Email – mines@nirma.co.in, umeshbhavsar@nirma.co.in

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhod Limestone Mine over an area of 71.52 ha located near Village- Bhod, Tehsil- Ranavav, District- Porbandar in Gujarat.


महोदय Sir.

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 9.7.2021 in the presence of Shri D.K.Singh /technical person rep.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	As per the approved Review of Mining Plan vide dated 16.10.2019 for the period 2019-20 to 2023-24. in the page 27 it is proposed to drill 28 no boreholes in the year 2020-21 but the same has not been drilled till date.
45(7)	While scrutiny of annual return for the financial year 2020-21 following discrepancies has been observed: (1) Part-I. Sr. No. 3 Post office and taluka have not given. (2) Part I. Sr No 9 – Name of geologist has not been mentioned. Violation has been pointed out in this regard. (3) Part-II. Sr No 1- No of whole time geologist has not mentioned.
55(1)(3)(i)	A whole time Geologist has not been appointed to carry out the duties as required under these rules.

2. In this connection. it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non-compliance of rule 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining and/or state Government may be informed to take actions as per competent directives.
4. To Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7). in case if it is found that the holder of a mining lease. has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.


भवदीय Yours faithfully.

  
4.8.21  
(R.Majumder)

Regional Mining Geologist

निम्नलिखित सूचनार्थ पत्र आवश्यक कार्यवाई हेतु प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- आयुक्त, भूविज्ञान एवं खनन, निदेशालय, गुजरात को सूचनार्थ पत्र आवश्यक कार्यवाई हेतु प्रेषित। (cgm@gujarat.gov.in).
- 3- DDG, MMS Division – for necessary action pl.
- 4- MCDR/गार्ड फाइल

  
4.8.21

Regional Mining Geologist

जारी किया/Issued  
4-8-21

o/c