



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES

No. ORI/IRON/SNG/MCDR-1(BIM)/BBS

प्रेषिति : Sri P. K. Rath, Chief General Manager & Agent,

M/s Steel Authority of India Ltd.,

Barsua Iron Ore Mines,

P.O. Tensa-770042,

Sundargarh, Odisha

Email: rmdbhubaneswar@gmail.com

विषय: Violation of provisions of MCDR, 2017 in respect of your Barsua Iron Mine over an area of 976.43 ha in Sundargarh district of Odisha State.

महोदय,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 12.04.2022 by the undersigned along with Shri Rajani Kanta Rautaray, AME of this office in presence of Sri P. K. Rath, Chief General Manager & Agent.

1. Barsua Iron Ore Mine

Mining operations in the mining lease are not being carried out in accordance with the proposal given in approved modified mining plan dated 01.04.2021 to the extent given below.		
Items	Proposal	Actual done
11(1) i) Exploration	109 Nos of boreholes were proposed to drill under G1/G2 category during the year 2021-22,	During inspection, it has been observed that only 69 nos. of bore holes have been drilled against the approved proposal.
ii) Back filling	During the year 2021-22, it was proposed for backfilling over an area of 7.884 Ha. in eastern side of the Area-3.	During inspection, it has been observed that only 2.0 Ha. of area has been backfilled against the proposal.
iii) Protective measures	During the year 2020-21, it was proposed to construct 750 m retaining wall (1.5mx1.0m) and 770m garland drain (1.5m x 1.0m) along the waste Dump.	During inspection, it has been observed that the retaining wall and garland drain have not completed as per the approved proposal.
45(5) (c)	The holder of a mining lease shall submit an annual return in respect of each mine to the Regional Controller or any other Authorized Official of the Indian Bureau of Mines before the 1st day of July each year for the preceding financial year in electronic form	On scrutiny, it is observed that (i) in item no. 5 of part-VI (Production, Dispatches & Stock), dispatch of 60-62% Iron Ore fines for domestic sale have been carried out to the consignee namely 3RD EYE without having the IBM registration (ii) in part -VII (Cost of production), production proposal for 2020-21 has been wrongly mentioned.

2. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम, 45(7)(क) के अंतर्गत

(क) खान की सारी खनन संक्रियाए बंद की जा सकती है ।

(ख) आपके विरुध अभियोग दायर किया जा सकता है ।

(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है ।

3. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे ।

भवदीय

(बी.एल.गुर्जर)

क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि- सुचनार्थ एवम आवश्यक कार्यवाही हेतु।

1. खान नियंत्रक (पूर्व), भारतीय खान ब्यूरो , कोलकाता Email-com.cz@ibm.gov.in

2. खान निदेशक, खान निदेशालय, ओडिशा सरकार, भुबनेश्वर - 751 001

3. श्री यू के भास्कर, खान प्रबंधक, बरसुआ आयरन ओर माइन, मेसर्स सैल, टैंसा, सुंदरगढ़, ओडिशा - 770042

(बी.एल.गुर्जर)

क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो