



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES

Violation Letter by registered post

Phone: 0674-2352463;
TeleFax: 0674-2352490;
eMail: ro.bhubaneswar@ibm.gov.in
Plot No.149, Pokhariput
BHUBANESWAR-751020
Date: 13.08.19



No. ORI/LST & DOL/SNG/MCDR-5/BBS VOL-III

Plot No. – 149, Pokhariput
In front of CPWD office,
Bhubaneswar – 751020

सेवा में,

✓ Shri S K Rout, Deputy Executive Director,
M/s OCL India Ltd,
At/Po- Rajgangpur, Dist- Sundargarh,
Odisha-770017

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Lanjiberna Limestone & dolomite mine over an area of 873.057 hectare in Sundargarh district of Odisha State.

Sir,

The following provision of Mineral Conservation and Development Rules, 2017 was found violated in your above said mine during inspection on 23.07.2019 by the undersigned along with Shri Jitendriya Pradhan, Assistant Mining Engineer in presence of your mine official Shri Subrat Mishra, Mines Manager.

Further, Mining Operation have not been carried out in accordance with the Modification to Review of Mining Plan approved vide Letter No. MSM/FM/37-ORI/BHU/2017-18 dated 25.01.2018 to the extent indicated below.

Rule No.	Proposal	Nature of Violation
11(1)	Number of boreholes proposed to be drilled in 2018-19 was 218 nos.	Number of boreholes actually drilled in 2018-19 was 10 nos only.
	Waste generation proposed for 2018-19 was 1510700 cum at stripping ratio of 1: 0.84	Waste generated in 2018-19 was 1016562 cum or 2170016 tones as per annual return for 2018-19 at stripping ratio of 1: 0.64
	Length of retaining wall proposed to be constructed in 2018-19 was 538 m.	Length of retaining wall constructed in 2018-19 was 150 m only.

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.
03. The mining operation can be suspended under Rule 11(2), if compliance of Rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

S. Mazumdar
13/08/19
(SUDIP RANJAN MAZUMDAR)
Senior Mining Geologist
Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.
2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Building / New Capital / Bhubaneswar-751 001.

✓
(SUDIP RANJAN MAZUMDAR)
Senior Mining Geologist
Indian Bureau of Mines