

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463; TeleFax: 0674-2352490; eMail: ro.bhubaneshwar@ibm.gov.in Plot No.149, Pokhariput BHUBANESWAR-751016 Date:18.08.2017

File No: ORI/GRPH/NUP/MCDR-05/BBS

To,

Shri Dilip Kumar Agrawal, Mine Owner Agrawal Graphite Industries, At: Shantikunj, Farm Road, P.O: Sambalpur, Odisha – 768 002

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Kirkita Graphite Mine in Nuapada District of Odisha, over an extent of 31.808 ha-Reg.

The following provisions of Mineral Conservation & Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above mine during inspection on 11.08.2017 by Shri N M Dey, Asstt. Mining Engineer, accompanied by your representative Shri R K Mishra, General Manager & Shri Jagadish Dash, Mines Surveyor.

Rule	Rule position	Status and extent of violation
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Minesor above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.	Mining operations have not been carried out in accordance with the Scheme of Mining approved vide letter number MS/OTFM/36-ORI/BHU/2015-16, dated 28.03.2016. The extent deviation is as given below: i) Exploration for the year 2016-17 was proposed 8 number of Bore Holes but no exploration has been carried out as per the proposal envisaged in para 4.9
26 (2)	The holder of mining lease shall submit a yearly	ii) Plantation proposed was 250 numbers during the year 2016-17 in the safety zone but no plantation was carried out as per the proposal envisaged in table 11.4 of the approved document for the said year. Yearly report for the year 2016-17 on protective and
	reportbefore 1 st day of July every year setting forth the extent of protective and rehabilitative works	rehabilitative works carried out as envisaged in the approved mine closure plan has not been submitted.
31	The plans and sections required under these rules shall be maintained up to date with in twelve months in case of any other mine.	The plans & sections have not been updated since 14.03.2016.
33	The holder of a mining lease shall, on or before the 30 th day of June every year submit copies of plans and sections tomaintained under rule 32.	Copies of plans and sections have not been submitted to this office.
35 (2)	Every holder of a mining lease shall monitor his mining and allied activities as per the notified template of star rating Self-assessment report before the 1 st day of July every year for the previous financial yearas on the 31 st day of march for that financial year	Notified template of star rating in the format prescribed for the year 2016-17 have not been submitted.

		A part-time mining engineer and a part-time geologist
v)	case of - category 'B' mines, a part-time mining	have not been appointed.
	engineer and a part-time geologist.	

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017. Besides, inability to comply the provisions of rule 11(1) also liable for suspension of mining operations under the provisions of rule 11(2) of MCDR, 2017.
 - 3. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

(D.UPADHY AY

Assistant Controller of Mines