



भारत सरकार/Government of India  
खान मंत्रालय/Ministry of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines  
क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa  
(आईएसओ-9001:2015)

Phone No.: (0832)-2741757  
Fax No. : (0832)-2741758  
E-mail : ro.goa@ibm.gov.in

Opp. R.T.O. Office,  
P.O. FATORDA – 403 602,  
MARGAO - GOA.

NO: KNT/BJP/LST-58/GOA

Mine Code: 38KAR26025

Date: 14/07/21

सेवा में/ To,

Shri H.G. Shreepada, Mine Owner  
Naganapur Limestone Mine  
Parimala, 9<sup>th</sup> Cross, Mahantesh Road, Vidyagiri.  
Bagalkot- 587 102  
Karnataka State

विषय/Subject: Violations of MCDR provisions in respect of Naganapur Limestone Mine, ML No. 2358 of Shri H.G. Shreepada, Extent 2.43 Ha., located at Naganapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 29.06.2021 by undersigned in presence of Shri H.G. Shreepada, Mine Owner and Arjun Kolachi, Permit Manager:

Rules	Nature of Violations observed
26 (2)	An yearly report before 1 <sup>st</sup> July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for the last year 2020-21.
35(2)	a) Online self-assessment report of star rating for the F.Y. 2020-21 in the format prescribed by the Indian Bureau of Mines is not found submitted by the lessee on or before 1 <sup>st</sup> July, 2021. b) High resolution satellite images obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on 31 <sup>st</sup> March for that financial year, covering the mining lease and an area of 2 kilometres from the lease boundary has not been submitted to the Regional Controller of Mines, IBM-Goa for the year 2020-21. [next page..]

45(5)(c)(i)	Annual Return for the F.Y. 2020-21 which shall be submitted on or before 1 <sup>st</sup> day of July, 2021 is not found submitted to the Regional Controller of Mines, Goa by the lessee.
55(1)(3)(iii)	The mine is being operated without employing a full time Mining Engineer and a full time Geologist as required under the provision of this rule.

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(Krishnendu Chatterjee)  
Senior Mining Geologist  
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director (Stat.), MMS Division, IBM-Nagpur.
3. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Krishnendu Chatterjee)  
Senior Mining Geologist  
Indian Bureau of Mines