VIOLATION LETTER SPEED-POST



भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINE

फैक्स: (080) 23371027 / 23373287

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

दूरभाष: 080-23371027 / 23375366/67

गोरगुंटापाल्या येशवंतपुर,

Email ID: ro. bangalore@ibm.gov.in

बेंगलुरु -560022

सं/No.: KNT/BLR/FE.414/BNG/Vol-1

दिनांक/Dated: .01/08/2019

सेवा में/To,

K.S.Nagaraj, Nominated Owner, Ramanamalai Iron ore Mine, VESCO House, 2/138, Ballari Road, Sandur - 583119.

विषय/Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Ramanamalai Iron Ore Mine, ML No. 2296 of M/s Veerabhadrappa Sangappa & Co., situated near Ramgad village, Sandur Taluka, Ballari district of Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 10/07/2019 by the undersigned accompanied by Sri Shanmukhappa Mandal, Sr.Manager and a representative of the lessee.

Rule No	Violations observed
11 (1)	Modification in the approved Mining Plan was approved vide letter no. 279/478/95/BNG
	dated 16/09/2016 for the period 2016-17 to 2020-21. The deviations observed in mining
	operations vis-a-vis approved document are given below.
	(i) During the year 2018-19, it was proposed to explore and convert G3 category
	area of 1.84 ha into G1 & G2 category by drilling 6 No. of boreholes (Core).
	But during the inspection it was observed that the proposed exploratory
	boreholes have not been drilled.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
- 03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(जी सी मीणा / G C MEENA)

क्षेत्रीय खान नियन्त्रिक / Regional Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department. of Mining & Geology, No.49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(जी सी मीणा / G C MEENA)

क्षेत्रीय खान नियन्त्रिक / Regional Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines