



VIOLATION LETTER

भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES

Phone: 0674-2352463;
TeleFax: 0674-2352490;
eMail:
ro.bhubaneswar@ibm.gov.in
Plot No.149, Pokhariput
BHUBANESWAR-751020

No.: ORI/CR/JJP/MCDR-16BBS-I/

Date: 14/12/2020

To

The Managing Director & Nominated Owner
M/s Odisha Mining Corporation Ltd.
OMC House, Bhubaneswar
Odisha - 751001

Sub: Violation of provisions of MCDR, 2017 in respect of your South Kaliapani Chromite Mines, over an area of 552.457 hectare in Jajpur district of Odisha State

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 12.12.2020 by the undersigned accompanied by S/Shri, K.K. Nayak, Junior Mining Officer, DDM Office, Jajpur Road, State Govt., Of Odisha, K Pradhan, Manager of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining plan dated 13.02.2018 i) It is proposed to construct retaining wall of 1900 m in length and garland drain of 1900 m in length around waste dumps as part of protective measures for the year 2019-20.	ii) During inspection it is observed that the retaining wall and garland drain have not been constructed around waste dumps during the year as per the proposal.
45 (5) & (7)	Holder of mining lease shall not submit incomplete or wrong or false information in daily or monthly or annual returns.	i) During scrutiny of annual return for the year 2019-20 it is observed that details furnished under Part-VI, item no.2(iii) the production quantity of concentrates furnished as 189.28 t during the year 2019-20, but during inspection it is observed that no such processing has been carried out for production of concentrates.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR,2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

(Ramkishan R)
Senior Assistant Controller of Mines
Indian Bureau of Mines