भारत सरकार खान मंत्रालय भारतीय खान ब्यूरो क्षेत्रीय खान नियंत्रक का कार्यालय

फाईल सं.: ORI/IRON-Mn/SNG/MCDR-12/BBS / 8-96Mine Code-300RI13012

दिः 21/07/2017

रोवा में.

Shri M.D. Rustagi Director & Nominated Owner M/s Feegrade & Co. Pvt. Ltd Rungta office, Main road Barbil, Dist: Keonjhar(Odisha)-758035

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Nadidih Iron & Manganese mine, over an extent of 121.405 hectare in Sundargarh District.

Sir,

The following provisions of MCDR,2017 were found violated in your above mine during inspection on presence of Sri H.S. Riswal, Geologist & Shri N.R. Satpathy, Mines Manager.

14/07/2017 by undersigned in presence of Sri H.S. Biswal, Geologist & Shri N.R. Satpathy, Whites Manager.	
Rule No.	Nature of violations observed
11(1)	Mining operations have not been carried out in accordance with the Modified Mining Plan,
11(1)	approved vide this office letter number MPM/FM/24-ORI/BHU/2016-17 dated 30.12.2016 to the
	extent given helow:
	1) In 2016-17, 1.0 million tonne of ROM production was proposed from low grade dump/stack.
	Whereas it has been observed that in 2016-17 only 0.214 million tonne ROM from ore has
	been handled from low grade dump/stack.
	2) In 2016-17, production of 3000Tonnes of manganese ore was proposed. Whereas during
	inspection it is observed that the Manganese pit has not been developed as per approved
	proposal and no production has been carried out.
	2) In 2016-17, a retaining wall of 903mX1.5mX1.0m and a garland drain of 903mX1.5mX1.0m
	were proposed around dump-C in north and western extension. Whereas it has been observed
	during inspection that only 50% of work has been completed.
-	4) In 2017 18 total 13nos of bore holes have been proposed to know the depth continuity of ore
	body while it has been observed during inspection that the proposed bore holes have not been
	started.

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Assistant Controller of Mines

OL

Indian Bureau of Mines

