## Government of India Ministry of Mines Indian Bureau of Mines

No. TN/PBR/LST/29.MDS

C 4 A Rajaji Bhavan Besant Nagar Chennai - 90.

Dated: 11 /03/2020

To:

The Agent (Mines)
Perianagalur Limestone Mine
M/s. Ramco Cements Ltd.
Govindapuram Works,
Sendurai Road,
Ariyalur – 621 730.

(Minecode 38TMN38045)

<u>Sub.</u>: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Perianagalur Limestone Mine over an area of 17.36 ha. in Perianagalur Village, Ariyalur Taluk & District.

Sir,

The following provision of the MCDR, 2017 was found violated in your above mine during the MCDR inspection on 5.3.2020 by the undersigned is accompanied by Sri K. Abraham, Manager (Mines),P.Senthamilselvan,Sr Manager(Gology) & Sri R.Jayaker,Mining Engineer.

Rule No.	Nature of violation observed
11(2)	Mining operations were not carried out in accordance with the proposals given in the approved ROMP to the extent indicated below:-
	For the year 2018-19, the working proposals as per the approved ROMP in between section line 2-2' to 3-3', with a depth of RL 68 m to RL 64 m. Similarly, for the year 2019-20, the proposals are in section line 2-2' to 3-3', with a depth of RL 64 m to RL 60 m. with a total depth of 8 m.
	During the inspection, it was observed that the working has reached upto 12 m. (56 mRL) depth. Further, working has been extended towards western side on section line 3-3', where there is no proposal and also observed that no working has been carried out on section 2-2' as proposed.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(2) is not found satisfactory.
- O4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(V. Jayakrishna Babu) Regional Controller of Mines

## Copy to:

- 1. The Controller of Mines(S), Indian Bureau of Mines, Bangalore.
- 2. The Commissioner of Geology & Mining, Govt. of Tamilnadu, Guindy, Chennai-32.