



भारत सरकार
Government of India
खान मंत्रालय
Ministry of Mines
भारतीय खान ब्यूरो
Indian Bureau of Mines

पंजीकृत पावती
उल्लंघन पत्र
माखुपूरा औद्योगिक क्षेत्र,
Makhupura Industrial Area
अजमेर-305 002 (राजस्थान)
Ajmer- 305 002 (Rajasthan)
फैक्स नं 0145.2695202 फोन नं 2695165

Mine Code: 30RAJ06001

संख्या : RAJ/BLW-426/IO-01

दिनांक : 18.02.2020

प्रेषित : Mine Agent
M/s Jindal Saw Ltd.,
Araji No. 9697/6711,
Near Tiranga Hills, Village-Pur,
Tehsil & District-Bhilwara 311 802 (Rajasthan)
Email- sunil.pandey@jindalsaw.com, dinesh.patil@jindalsaw.com

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Dhedwas Iron Ore, Copper & Associate Minerals Mine (Lease area 1556.7817 Ha.) in Bhilwara District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 22.01.2020 & 23.01.2020 by the undersigned in presence of Sh. Dinesh S Patil, Mine Agent:

Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified Mining Plan: 1) Under future exploration programme, there was proposal to drill 03 bore holes during the year 2018-19, but these proposed bore holes have not been drilled so far. 2) No proper terracing of various waste dumps has been carried out. 3) Benches have not been properly developed as per approved proposals. 4) Location of proposed bore holes for the year 2019-20 have been changed as per your notice of sinking of bore holes in Form-I submitted to this office vide your letter dated 29.11.2019.
Rule 26 (2)	A yearly report to be submitted before 1 st July of every year setting forth the extent of protective and rehabilitation works carried out as envisaged in the approved progressive mine closure plan has not been submitted to this office for the year 2018-19.
Rule 45(7)	In annual return 2018-19 following discrepancies were observed: 1) Under item 3 of Part IV, the OB removed has been shown 2160256 tonnes whereas in item 4.2 (C) (ii) during the year 6048717 tonnes of OB/Waste has been dumped in external dumps.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

(क) आपकी खदान की सारी संक्रियाएं बंद की जा सकती है।

(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।

03. अतः आपको यह निर्देशित किया जाता है कि आप आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को प्रेषित करें।

(डी. आर. गुर्जर)
वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ईमेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, भीलवाड़ा।
- 4 रक्षित पत्रावली।

वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो