## Speed post /तीव डाक

भारतसरकार खानमंत्रालय भारतीय खानब्यूरो क्षेत्रीय खाननियंत्रक काकायांलय माखुपुराओद्योगिक क्षेत्र अजमेर 305002 ई—मेलः ro.ajmer@ibm.gov.in





Mine Code: 38RAJ13008

Violation letter/उल्लंघन पत्र

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.
Makhupura Industrial Area, Ajmer- 305002
Ph-145-2695165 / 2695476 Fax-2695202

दिनांक:18/10/2019

संख्या : RAJ/JPR-115/Lst-03

To: SHANN YOUR NO.

To: Sri M.L. Lahoti, Mine Agent, Mohanpura Jodhpura Limestone Mine,

M/s Ultratech Cement limited,

Village: Mohanpura, Tehsil: Kotputli,

District: Jaipur (Rajastaha),

PIN: 303108.

 $(e\text{-}mail: \underline{manoharlal.lahoti@adityabirla.com} \ , \ \underline{rahul.gopalia@adityabirla.com} \ )$ 

বিষয়: Violation of provision of Mineral Conservation and development rule 2017 in respect of your Grasim Cement Limestone Mine in Jaipur district of Rajasthan State.

महोदय.

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above said mine during inspection on 04/10/2019 by the undersign along with Sri Rajani Kanta Rautaray, AME in presence of Sri Rahul Gopalia, Mine Manger and Sri P.S. Mishra, Geologist of your Mine:

Rule	Status and extent of violation
11(1)	Mining operations have not been carried out in accordance to Modification in Review of Mining Plan approved vide letter number 584(6)(3)(561)/2014/RCOM-AJM dated 11/11/2014 to the extent given below:
	(1) During the year 2018-19, a quantity of 483791 CuM of waste (Soil+Waste rock) has been proposed to generate, however a quantity of 1313621 CuM (2370673 tonnes) of waste has been generated during the year 2018-19.
	(2) The stripping ratio has been proposed to 1:0.11 CuM/Tonnes for the year 2018-19, however, stripping ratio achieved during the year 2018-19 was 1:0.32 CuM/Tonnes.
12(1)	Retaining wall and garland drain has not been provided in the interest of protection of environment along the tow of the waste dump number -04 to arrest surface runoff.

- 02. It is brought to your notice that above violations of MCDR, 2017 constitutes an offence punishable under Rule 62 of MCDR, 2017.
- 03. Inability to comply the provision of MCDR, 2017 following action may be initiated against you:
- (i) order suspension of all mining operations in the mine.
- (ii) take action to initiate prosecution under these rules;
- (iii) recommend termination of the mining lease.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

ि हि हि हि हि हि (दिलीप जैन) यरिष्ठ खनन भूवेज्ञानी भारतीय खान ब्यूरो

## प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खिन अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, Jaipur (Raj.).
- 4 रक्षित पत्रावली।

( दिलीप जैन ) वरिष्ठ खनन मूर्विज्ञानी भारतीय खान व्यूरो