भारतीय खान ब्यूरो क्षेत्रीय खान नियंत्रक का कार्यालय

56 (1)

रजिस्टर्ड ए०डी०

संख्या

एचपी / एसआरएम / एलएसटी-24

108, नेहरू नगर–2, देहरादून (उत्तराखण्ड), दिनांक : 13.05.2014

प्रेषक

उप खान नियंत्रक एवं प्रभारी अधिकारी

भारतीय खान ब्यूरो।

सेवा में :

मैं जेंoएस0 डाकुर एण्ड संस, द्वारा श्री आरoपीoतिवारी, देवीनगर, पावंटासाहिब, सिरमौर (हिमाचल प्रदेश)

विषय

Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect

of your Bohar Limestone Mine in Sirmour District of Himachal Pradesh.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection made by Shri S. Saklani, Assistant Mining Geologist on 04.01.2014 and communicated to you vide this office registered A/D letter of even number dated 21.03.2014 giving you a period of 45 (forty five) days for rectification. Subsequently the mine was inspected by Shri A.K. Vig, Assistant Mining Geologist on 14.04.2014 and similar violations were observed.

Rule No.	Nature of violation observed in detail
13 (i):	(i) The scheme of mining for this mine was approved on 22.12.2011. Therefore proposals incorporated in the scheme for the second year were examined. It was proposed that mining shall be carried out for excavation of limestone by formation of 14 benches at top, middle and bottom part having three mtrs height with 6 & 10 mtrs width. During the inspection it was observed that mining operations were carried out in by formation of five benches only with height ranging from 6 to 7 mtrs each. (ii) It was proposed in the scheme of mining that 37 mtrs long retaining wall shall be erected along the dump. During the inspection it was observed that nearly 10mtrs long retaining wall has been erected only and a substantial quantity of dump was also not dumped at earmarked place. (iii) It was proposed that dump yard shall be created for the western block on northern side of the lease but no such dump yard has been observed.
02.	However, it has been found that the reply furnished by you in compliance to Rule 13(1) was duly considered & found unsatisfactory.
03.	It is brought to your notice that Violation of above rule constitutes an offence punishable under Rule 58 of Mineral Conservation and Development Rules, 1988 and may lead to suspension of mining operation under rule 13(2) of MCDR 1988
04.	You are, therefore, directed to show cause within a period of 30 (thirty) days from the date of issue of this letter as to why you should not be prosecuted for the violation above Rules and your mining operation should not be suspended under Rule 13(2) of MCDR 1988
05.	Please note that no further notice will be given to you in this regard.

105. SIC

(जी०सी०मीणा)

उप खान नियंत्रक एवं प्रभारी अधिकारी भारतीय खान ब्यरो

प्रतिलिपि सूचनार्थ-

1- खान नियंत्रक (उ०), भारतीय खान ब्यूरो, अजमेर।

2. निदेशक, उद्योग विभाग, उद्योग भवन, हि०प्र०सरकार, शिमला । क्रिया

(जी०सी०मीणा) उप खान नियंत्रक एवं प्रभारी अधिकारी भारतीय खान ब्यूरो