## Speed post

भारतसरकार खानमंत्रालय भारतीय खानब्यूरो क्षेत्रीय खाननियंत्रक काकार्यालय माखुपुराओद्योगिक क्षेत्र अजमेर 305002 ई—मेलः ro.ajmer@ibm.gov.in





## **Violation Letter**

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.
Makhupura Industrial Area, Ajmer- 305002
Ph-145-2695165 / 2695476 Fax-2695202

दिनांकः 12/11/2020

संख्या : RAJ/UDP/Pb-Zn-01/Vol-VII

To: Mine Agent,

Mochia Pb-Zn Mine,

M/s Hindustan Zinc Limited,

Village: Zawar,

District: Udaipur (Rajastaha),

PIN: 313901.

(e-mail: Kishore.S@vedanta.co.in)

विषयः Violation of provision of Mineral Conservation and development rule 2017 in respect of your

Mochia Lead-Zinc Mine in Udaipur district of Rajasthan State.

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above said mine during inspection on 27/10/2020 by undersign in presence of Sri Sanat Kumar, Mine Manager and Sri Vivek Tyagi, Geologist of your Mine:

Mining operations have not been carried out in accordance to Modified Mining Plan
approved on 17/05/2019 to the extent given below:  (1) During year 2019-20, a total of 413 exploratory bore holes with 39000 mts of drilling were proposed from underground and Surface. However, during inspection it is reported that a total of 315 bore holes with 53922.00 mts of drilling were carried out during the year 2019-20.  (2) As per approved document planation has been proposed in Pratap Pura area between grid 8020 E to 8610E and 12780N to 13580 N. However, it is observed that plantation has not carried out over proposed area.
The yearly report on extent of protective and rehabilitative works carried out as specified in the rule has not been submitted to the Regional Controller of Mines (competent authority) for the year 2019-20.
As specified in the rule, soft copy (in the standard format), of high resolution satellite images obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map as specified in the Rule has not been submitted to the Regional Controller of Mines, Ajmer.
On examination of annual return for the year 2019-20 following discrepancies have been observed.  (1) Part-I, Section-12: The details of lease area (surface area) utilization has not been shown.  (2) Part V: In section 1 grade of Mineral Reject has been furnished as 1.01 % (Pb & Zn) whereas, the grade of mineral reject has been furnished as 0.75 % in section 4.  (3) Part V, section 7: During inspection it was reported that Pb-Zn Ore is being feed to the beneficiation plant located in Mochia Mine boundary. However, details required under section 7 of part V in connection with beneficiation plant have not been furnished.  (4) Part VII: Cost of beneficiation has also not been furnished. Further, amount paid towards

02. Further, this to bring in your kind notice that no reply yet has been received in respect of the violation issued vide this office letter of even number dated 03/12/2019.

03. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

- (क) आपकी खदान की सारी संकियाएं बंद की जा सकती है।
- (ख) आपके विरूध्द अभियोग दायर किया जा सकता है।
- (ग) राज्य सरकारा को खनन पट्टे की समप्ति की सिफारिश ।

04. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैतालिस) दिनों के भीतर इस कार्यालय को सूचित करें।

> (दिलीप जैन) वरिष्ठ खनन भूविज्ञानी भारतीय खान ब्यूरो

## प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान व्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता. खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 4 रक्षित पत्रावली।

( दिलीप जैन ) वरिष्ठ खनन भूविज्ञानी भारतीय खान ब्यूरो