## INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### MCDR INSPECTION REPORT

### Gandhinagar regional office

Mine file No : RAJ/UDP/CAL-34 Mine code: 09RAJ26006

(i)Name of the Inspecting : G021 ) DATA RAM GURJAR

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Sh. Prakashchandra Sanghvi & Sh. Nimish Singhvi, QP

Official with

Designation

(iv) Date of Inspection : 07-JUL-21 Prev.inspection date : 01-FEB-19 (v)

PART-I : GENERAL INFORMATION

(a) Mine Name : TEJA-KA-VAAS

(b) Registration NO. : IBM/9972/2012

(C) Category : B Manual (d) Type of Working Opencast

(e) Postal address

> State : RAJASTHAN District UDAIPUR

Village TEJA-KA-VAAS

Taluka KOTRA

Post office Pin Code : FAX No.

: E-mail rameshmutha@gmail.com

9660856649/9824940540 SIROI Phone

(f) Police Station : BEKARIYA First opening date : 01-JAN-01 (g)

Weekly day of rest (h) : SUN

Address for : BEHIND AKASH COLONY

correspondance SIROHI ROAD

DISTT- SIROHI RAJASTHAN

3. : RAJ0059 (a) Lease Number (b) Lease area : 112.5 Period of lease : 20 (C)

> (d) Date of Expiry : 22-SEP-03

Mineral worked 4. : CALCITE Main

PAGE: 2

5. Name and Address of the

Lessee : HINDUSTAN MINERAL TRANSACTION

OPP VIKAS COLONY SIROHI ROAD DISTT- SIROHI SIROHI

RAJASTHAN Phone:
FAX:

Owner : RAMESH KUMAR MUTHA

4 MAHAVEER COLONY EVK SAMPATH ROAD , VEPERY CHENNAI SIROHI RAJASTHAN

Phone: 09982007793

FAX :

6. Date of approval of Mining : Renewal under rule 22 MCR1960 21-AUG-03 Plan/Scheme of Mining : Modif.of approved Mining Plan 21-APR-05

PAGE : 3

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

# Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	No approved proposals for the year 2019-20. earlier scheme of mining was was valid up to year 2015-16.	No exploration has been carried out.	Mining operations are discontuied for a long time. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
1b	Exploration over lease area for geological axis 1 or 2	Not specified	Not applicable	Current inspection has been carried for Review of mining plan. Proposal for entire mineralised area exploration has been asked in fair copies of Review of Mining Plan vide this office scrutiny comments dated 20.07.2021.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No proposal of exploration during the last year.	None	Nil
1d	Balance area to be explored to bring Geological axis in 1 or 2	No proposal	None	Current inspection has been carried for Review of mining plan. Proposal for entire mineralised area exploration has been asked in fair copies of Review of Mining Plan vide this office scrutiny comments dated 20.07.2021.
1e	Balance reserve as on 01/04/20	Not specified.	As per earliear appoved scheme of mining (Approved on 04.11.2011): Wollastonite Reserve: 2766926 tonnes.	However in the scrutiny comments of submitted draft review of mining plan, qualified person advised to recalculate R & R as per norms of MEMC Rules 2015.

1f General remarks of inspecting officers on geology, exploration etc

(1)Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. (2)Current inspection has been carried for Review of mining plan. Proposal for entire mineralised area exploration has been asked in fair copies of Review of Mining Plan vide this office scrutiny comments dated 20.07.2021.

## Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area		None.	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	proposal for	Nil	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.

2c	Stripping ratio or ore to OB ratio	No approved proposal for the year 2020-21.	Nil	Mining operations are discontuled for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
2d	Quantity of topsoil generation in m3	No approved proposal for the year 2020-21.	Nil	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
2e	Quantity of overburden generation in m3	No approved proposal for the year 2020-21.	Nil	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018.
Exp	loitation:			

Actual work

Remarks

Sl.No.

Item

Propasals

Number of pit proposed for production

No approved None proposal for the year 2020-21.

Quantity of ROM 3b mineral production proposed

No approved None proposal for the year 2020-21.

3с Recovery of sailable/usable mineral from ROM the year 2020production

None No approved proposal for 21.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

3d Quantity of mineral reject generation

No approved None proposal for the year 2020-21.

3e rejects generation and threshold value declared.

Grade of mineral No approved None proposal for the year 2020-21.

3f Quantity of sub No approved grade mineral generation.

None proposal for the year 2020-21.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

3q Grade of sub No approved Mining operations None grade mineral proposal for are discontuied generation the year 2020for last many 21. years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan. 3h Manual / No approved None Mining operations Mechanised are discontuied proposal for for last many method adopted the year 2020for segregating years. No valid 21. from ROM mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan. 3i Any analysis or No approved Mining operations None beneficiation proposal for are discontuied study proposed the year 2020for last many and carried out years. No valid 21. for sub grade mining plan of the mineral and mines. Mining rejects. operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan. Provision of No approved Nil 3 ј None drilling and proposal for blasting in the year 2020mineral benches 21. 3k Provision of No approved NilNone mining proposal for machineries in the year 2020-

mineral benches

21.

31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	No approved proposal for the year 2020-21.	None	Nil
3m	Total area covered under excavation/pits	No approved proposal for the year 2020-21.	Last scheme of mining was valid up to 2015-16. However as per submitted draft review of mining plan the area under mining is 0.3603 hect. area.	Nil
3n	Ore to OB ratio for the pit/mine during the year.		None	Nil
30	Total area put in use under different heads at the end of year	No approved proposal for the year 2020-21.	Last scheme of mining was valid up to 2015-16. However as per submitted draft review of mining plan the currently total area put to use under different heads is 5.6665 hect. including plantation.	Nil
3p	Production of ROM mineral during the last five year period as applicable	No valid approved proposal during the last five year i.e. 2016-17 to 2020-21.	Not reported by the lessee.	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
3q	General remarks of inspecting officers on method of mining etc.			

Actual work

Remarks

Solid Waste Management - Dumping:

Propasals

Sl.No.

Item

4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No approved proposals for Seperate dumping in year 2020-21.	None	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
4b	Location of topsoil, OB and mineral reject dumps	No approved proposals for the year 2020-21.	None	Nil
4c	Number of dumps within lease area and outside of lease area	No approved proposals for the year 2020-21.	One very small old waste dump.	Nil
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	No approved proposals for the year 2020-21.	Close to pits within UPL	Nil
4e	Number of active and alive dumps.	No approved proposals for the year 2020-21.	None	Nil
4f	Number of dead dumps.	No approved proposals for the year 2020-21.	One	Nil
<b>4</b> g	Number of dumps established.	No approved proposals for the year 2020-21.	None	Nil
4h	Whether Retaining wall or garland drain all along dumps are there.	proposals for	None	Nil
4i	Length of Retaining wall or garland drain all along dumps	No approved proposals for the year 2020-21.	None	Nil
<b>4</b> j	Number of settling ponds	No approved proposals for the year 2020-21.	None	Nil

4k Specific comments of inspecting officer on waste dump management

Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

## Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No approved proposals for the year 2020-21.	None	Mining operations are discontuied for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
5b	Area under backfilling of mined out area	No approved proposals for the year 2020-21.	None	Nil
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No approved proposals for the year 2020-21.	None	Nil
5d	Total area fully reclaimed and rehabilitated	No approved proposals for the year 2020-21.	None	Nil

5e General remarks of inspecting officers on backfilling and reclamation etc.

Mine not working for the last many years. Earliear the mining operations carried out at very small scale only. The area is not matured for backfilling & reclamation.

### Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	PMCP report shall be submitted up to 1 July for the previous financial year.	Not submitted.	Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
6b	Area available for rehabilitation (ha) .	No approved proposals for the year 2020-21.	None	Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
бс	afforestation done (ha).	No approved proposals for the year 2020-21.	None	Nil
6d	No. of saplings planted during the year	No approved proposals for the year 2020-21.	None	Nil

6e	Cumulative no .of plants	No approved proposals for the year 2020-21.	Not reported.	Nil
6f	Any other method of rehabilitation	No approved proposals for the year 2020-21.	None	Nil
6g	Cost incurred on watch and care during the year	No approved proposals for the year 2020-21.	Nil	Nil
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	No approved proposals for the year 2020-21.	None	Nil
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No approved proposals for the year 2020-21.	None	Nil
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	No approved proposals for the year 2020-21.	None	Nil
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No approved proposals for the year 2020-21.	None	Nil
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No approved proposals for the year 2020-21.	None	Nil
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	No approved proposals for the year 2020-21.	None	Nil

6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	No approved proposals for the year 2020-21.	None	Nil
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	No approved proposals for the year 2020-21.	None	Nil
бр	Compliance of environmental monitoring (core zone and buffer zone)	No approved proposals for the year 2020-21.	Not monitored	Nil
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

## Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No approved proposals for the year 2020-21.	None	Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	No approved proposals for the year 2020-21.	None	Mine is not working for last many years.
7c	Different grade of mineral sorted out at mines.	No approved proposals for the year 2020-21.	None	Nil
7d	Any beneficiation process at mines .	No approved proposals for the year 2020-21.	None	Nil
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	proposals for	None	Mines is not working for last many years. No valid mining plan of the mines. Mining operation also suspended by this office vide letter dated 13.11.2018. Current inspection carried out for submitted draft review of mining plan.
d8	Concurrent use or storage of topsoil	No approved proposals for the year 2020-21.	None	Nil

8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No approved proposals for the year 2020-21.	None	Nil
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No approved proposals for the year 2020-21.	None	Nil
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No approved proposals for the year 2020-21.	None	Nil
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No approved proposals for the year 2020-21.	None	Nil
8g	Survival rate	No approved proposals for the year 2020-21.	Not reported	Nil
8h	Water sprinkling on roads to control airborne dust	proposals for	Not observed.	Nil
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			Aesthetic beauty is good in and around mine area. Mine is not wrking for last many years. Earlier only very small scale mining has been carried out.

Actual work

Remarks

Compliance of Rule 45:

Propasals

Item

Sl.No.

9a	Status of submission of Monthly and Annual returns	the last year & current year.	For non submission of statuary returns under MCDR 2017, State Govt. informed regularly and requested to take appropriate action. Mine is not working for last many years. This office also suspended mining operation vide letter dated 12.11.2018.	Nil
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Annual return not submitted for year 2020-21.		For non submission of statuary returns under MCDR 2017, State Govt. informed regularly and requested to take appropriate action. Mine is not working for last many years. This office also suspended mining operation vide letter dated 12.11.2018.
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	not submitted	Due to non submission not scrutinized.	Nil
9d	Scrutiny of Annual return on afforestation		Due to non submission not scrutinized.	Nil
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)		Due to non submission not scrutinized.	Nil
9f	Scrutiny of Annual return on ROM stock and/or graded ore	not submitted	Due to non submission not scrutinized.	Nil
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost		Due to non submission not scrutinized.	Nil
9h	Scrutiny of		Due to non submission not scrutinized.	Nil

Scrutiny of Annual return Due to non submission Nil Annual return on not submitted not scrutinized. 9k

for year 2020mining

machineries 21.

PAGE: 19

Details of violations observed during current inspection and compliance position of violation pointed out								
Violation observed			Show couse position					
Rule NO.	Issued on Compliance	on	Rule NO.	Issued on Compliance on				

Date : (DATA RAM GURJAR)

Indian Bureau of Mines