

VIOLATION LETTER
By Registered Post Ack. Due

भारत सरकार/ **Government of India**
खान मंत्रालय/ **Ministry of Mines**
भारतीय खान ब्यूरो/ **Indian Bureau of Mines**
हैदराबाद क्षेत्रीय कार्यालय/ **Hyderabad Regional Office**

Phone No. : (040)-27539992/2753993
Fax No.(TF): (040)-27539991
E-Mail : ro.hyderabad@ibm.gov.in
File No. AP/KNL/LST-170/HYD.

603, 6th Floor,
CGO Towers, Kavadiguda,
Secunderabad – 500 080.
Date: 21.5.2018

To,

Shri P VenkatakrishnaYadhav, Agent
Korumanapalli Limestone Mines
M/s Penna Cement Industries Limited
Penna Nagar, Urichintal Post
Tadipatri Mandal-515415,
Dist.-Anantpur (A.P.)

Sub: Violation of Provisions of MCDR, 2017 in respect of your Korumanapalli Limestone Mines over an extent of 205.212 Ha situated in Korumanapalli Village, Tadipatri Mandal, Kurnool district of Andhra Pradesh State.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017, were found violated in your above mine during the inspection of the mine on 08.03.2018 by the undersigned and accompanied by your good self, Shri M Ramakrishna, Mines Manager and Shri M Ramesh Babu, Geologist of your mine.

Rule no.	Rule position	Nature of violation
11(1)	Every holder of a mining lease shall carry out mining operations in accordance with the approved mining plan with such conditions as may have been prescribed under sub-rule (2) of rule 9 or with such modifications, if any, as permitted under rule 10 or the mining plan or scheme approved under rule 11 or 12 as the case may be.	Mining operations are not carried out in accordance with the proposals given in approved Scheme of Mining vide letter no. AP/KNL/MP/Lst-94/HYD dated 30.03.2017 to the extent indicated below: i. It was approved to carryout mining operations in Eastern side of mining lease in Pit no.3 for development and production by maintaining bench height of 8 meters and width 20 meters during the year 2017-18, against which it was observed during inspection that production and development is being carried out in Western side of the lease in Pit no.1 in addition to the pit no.3 in Eastern side of the lease with bench height of more than 10 meters. ii. Mining operations are being carried out within 7.5 meters of the lease area in 'pit no.1' without having any such approved proposals. iii. Refer page no. 43, no proposal of crushing activity was approved in the lease area, but during inspection it was observed that crusher has been established in 'pit no.1' in the lease area.

		iv. Backfilling was observed in the pit no. 1 without having any such approved proposals.
31(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine.	During inspection it was observed that plans and sections were not maintained updated
67.	Obligation to supply other information. The holder of a mineral concession shall furnish such information regarding his reconnaissance or prospecting operations or mining operations or any matter connected therewith as the authorised officer may require by an order in writing and the information shall be furnished within such time as may be specified in the such order.	Copy of lease sketch along with Co-ordinates (WGS 84) of lease boundary pillars of the lease area should be furnished

02. In this connection, it is brought to your notice that the above violation constitutes an offence punishable under rule 62 of MCDR, 2017. Besides inability to comply the provision of rule 11(1) is also liable for suspension of mining operations under the provision of rule 11(2) of MCDR, 2017.
03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(IBRAHIM SHARIEF/ ईब्राहिम शरीफ)

Sr. Assistant Controller of Mines/ वरिष्ठ सहायक खान नियंत्रक

मूल प्रति पर नहीं/Not on the Original:

- 1^प खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।
2. The Director of Mines & Geology, Government of Andhra Pradesh, Hyderabad.
3. The Assistant Director of Mines & Geology, Government of Andhra Pradesh, Banganapalli, Kurnool district.A.P
- a. For kind information and further necessary action please: **Lease boundary pillars have not been posted as required under the provisions of Minerals (Other than Atomic and Hydro Carbons Energy Minerals) Concession Rules 2016.**

(IBRAHIM SHARIEF/ ईब्राहिम शरीफ)

Sr. Assistant Controller of Mines/ वरिष्ठ सहायक खान नियंत्रक

भारत सरकार/ Government of India
खान मंत्रालय/ Ministry of Mines
भारतीय खान ब्यूरो/ Indian Bureau of Mines
हैदराबाद क्षेत्रीय कार्यालय/ Hyderabad Regional Office

Phone No. : (040)-27539992/2753993
Fax No.(TF): (040)-27539991
E-Mail : ro.hyderabad@ibm.gov.in
File No. AP/KNL/LST-170/HYD.

603, 6th Floor,
CGO Towers, Kavadiguda,
Secunderabad – 500 080.
Date:

CORRIGENDUM

To,

Shri P VenkatakrishnaYadhav, Agent
Korumanapalli Limestone Mines
M/s Penna Cement Industries Limited
Penna Nagar, Urichintal Post
Tadipatri Mandal-515415,
Dist.-Anantpur (A.P.)

Sub: Violation of Provisions of MCDR, 1988 in respect of your Korumanapalli Limestone Mines over an extent of 205.212 Ha situated in Korumanapalli Village, Tadipatri Mandal, Kurnool district of Andhra Pradesh State.

Ref: This office letter of even no. dated 18.05.2018.

Sir,

This has reference to the above cited letter on the subject mentioned. In this connection it is to inform that this office has issued violations under various rules of Mineral conservation and Development Rules, for deviations and mentioned the Year, rule no. inadvertently due to typographical error as.

- 1. MCDR 1988 and Tadipatri Mandal in Sub, be read as:**
MCDR 2017 and Kolimigundla Mandal
- 2. Mineral conservation and Development Rules, 1988 in para1, be read as**
Mineral conservation and Development Rules, 2017
- 3. Rule No.13(1) be read as**
Rule No. 11(1)

Yours Sincerely,

(IBRAHIM SHARIEF/ ईब्राहिम शरीफ)

Sr. Assistant Controller of Mines/ वरिष्ठ सहायक खान नियंत्रक

मूल प्रति पर नहीं/Not on the Original:

- 1^प खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।
2. The Director of Mines & Geology, Government of Andhra Pradesh, Hyderabad.
3. The Assistant Director of Mines & Geology, Government of Andhra Pradesh, Banganapalli, Kurnool district.A.P

(IBRAHIM SHARIEF/ ईब्राहिम शरीफ)

Sr. Assistant Controller of Mines/ वरिष्ठ सहायक खान नियंत्रक

Sl.No	ML Pillar No	Latitude	Longitude
1	BP-10	14°59'19.08"	78°06'47.42"
2	BP-19	14°59'04.17"	78°06'49.14"
3	BP-22	14°59'3.51"	78°07'0.42"
4	BP-62	14°58'43.87"	78°06'57.87"
5	BP-66	14°58'38.74"	78°06'49.37"