

## भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES

## भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67 Email ID: ro. bangalore@ibm.gov.in. 29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,

गोरग्ंटापाल्या येशवंतप्र,

बेंगल्र -560022

सं. KNT/GLB/Lst-17/BNG

दिनांक:01.04.2021

सेवा में /To.

Shri. Ravindra Lagwankar, Agent Mines, M/s Vasavadatta Cement, Taluk: Sedam, Dist. Kalaburagi, Karnataka-585222

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Injepalli Limestone Mine (ML-2417) over an area of 897.86 Ha located in Injepalli Village, Sedam Taluk ,Kalaburagi District of Karnataka State.

## महोदय/Sir,

The following provisions of Mineral Conservation and Development Rules, 2017, were found violated in your above mine during the inspection on 12.12.2020 by Sri Arun Kumar, Deputy Controller of Mines and communicated to you vide this office registered letter of even number dated 09/02/2021 giving you a period of **45** (**Forty Five**) **days** time for rectification of the same.

Rule	Nature of violations observed
11(1)	Modified RMP including PMCP was approved vide letter no. 279/168/90/BNG dated 15.12.2017 for a period of 2017-18 to 2021-22. The deviation observed in mining operation vis-a-vis approved document are given below
	Development was proposed in Pit A: N-1200 to 557 & E -600 to 417. During the inspection it was observed that very little development has been carried out in Pit A in between section lines E-E' to H-H' in year 2019-20.
26 (1)	3000 saplings were proposed covering 0.44 Ha area on the soil bund made along mine boundary for green belt development, where as only 1955 saplings planted with 52% survival rate.

- 02. Till date you have not complied the pointed out violation and the reply received from you vide your letter no. VC/WS/Mines/48/2020-21 dated 05/03/2021 has been examined and is not found satisfactory. No supporting documents have been provided with the reply letter.
- 03. It is again brought to your notice that these violations constitute an offence punishable under rule 62 of MCDR 2017. On non compliance of the above provisions of MCDR 2017, the mining operation can be suspended under the rule 11(2) of the above mentioned rules.
- 04. You are therefore, directed to show cause within a period of 30 (thirty) days from the date of issue of this letter as to why your mine should not be suspended for the above offence.
- 05. Please note that no further notice will be given to you in this regard.

भवदीय/Yours faithfully,

Sd/-(वि जयकृष्णा बाब्) क्षेत्रीय खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

क्षेत्रीय खान नियंत्रक भारतीय खान ब्यूरो