



VIOLATION LETTER

भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463;
TeleFax: 0674-2352490;
eMail:
ro.bhubaneswar@ibm.gov.in
Plot No.149, Pokhariput
BHUBANESWAR-751020

No.: ORI/IRON/CDR-54/BBS/II

Date: 06/09/2019

सेवामें,
Shri Prashant Ahluwalia, Nominated Owner
M/s Kaypee Enterprises
Near MMTC weigh Bridge, Post Box No-3. P.O: Barbil
Dist- Keonjhar, Odisha,

Sub: Violation of provisions of MCDR, 2017 in respect of your Thakurani Iron Mines, over an area of 228.04 hectare in Keonjhar district of Odisha State

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 22.08.2019 by the undersigned along with Shri S.R.Mazumdar, SMG, IBM, Bhubaneswar accompanied by S/Shri S.K.Ghosh, Senior Inspector of Mines, DDM Office, Joda, State Govt., Of Odisha, Rabindranath Mandal, Manager of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining plan dated 04.06.2018 i) It is proposed to do production of 8 Million tones ROM Iron ore by generation of 1488502 cu.m. of waste with a stripping ratio of 1:0.18 t/cu.m during the year 2018-19. ii) It is proposed do dump plantation on dump-3 to the extent 4.3 Ha during the year 2018-19. iii) It is proposed to construct garland drain of 2650 m in length around waste dump.	i) During inspection it is observed that 5.49 million tonnes of ROM Iron ore is produced by generating 389395 cu.m. of waste with a stripping ratio of 1:0.07 t/cu.m. which is not a proportionate development with respect to ROM production during the year. ii) During inspection it is observed that dump plantation on dump-3 to the extent of area 4.3 ha has not been carried out. iii) During inspection it is observed that garland drain has not been constructed.
45 (7)	Holder of mining lease shall not submit incomplete or wrong or false information in daily or monthly or annual returns.	i) During scrutiny of annual return it is observed that lease area utilization details furnished under Part-I, item no.12 are not in line with the details of approved mining plan.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR,2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

Further, in view of the above position, the information furnished under Rule 45(5) in the Annual return is construed as furnishing wrong or false information, which leads this office to advise the state government under rule 45 (7) to,-

- (i) Order suspension of all mining operations in the mine and to revoke the order of suspension only after ensuring proper compliance;
- ii) Take action to initiate prosecution under these rules;
- (iii) Recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

R. Ramkishan R
(Ramkishan R)

Senior Assistant Controller of Mines
Indian Bureau of Mines

मूलप्रतिपर नही/ Not on Original प्रतिलिपिनिम्नकोसादरसूचनार्थअग्रेषित

- (1) **The Controller of Mines (EZ), भारतीय खानब्यूरो / Indian Bureau of Mines, Kolkata-700091.**
- (2) **डायरेक्टरऑफमाइन्स / The Director of Mines, डायरेक्टोरेटऑफमाइन्स / Directorate of Mines, उड़ीसासरकार / Government of Orissa, हेडसऑफडिपार्टमेंटबिल्डिंग / Heads of Department Building, न्यूकैपिटल / New Capital, भुवनेश्वर / Bhubaneswar-751 001 : For information**

R. Ramkishan R
(Ramkishan R)

Senior Assistant Controller of Mines
कृते क्षेत्रीय खाननियंत्रक / For Regional Controller of Mines