



भारत सरकार/**Government of India**
खान मंत्रालय/**Ministry of Mines**
भारतीय खान ब्यूरो/**Indian Bureau of Mines**
हैदराबाद क्षेत्रीय कार्यालय/**Hyderabad Regional Office**



F.No. AP/RR/LST-04/HYD

603, छठा तल /603, 6th Floor,
सी.जी.ओ.टॉवर्स/CGO Towers,
कवाड़ीगुड़ा /Kavadiguda,
सिकन्दराबाद/Secunderabad-500 080.
Date: 21/9/2021

To
The Agent(Mines),
Sangamkalan Limestone Mine-II,
M/s India Cements Limited,
Sangamkalan Village,Tandur Mandal,
Vikarabad District-501158,
Telangana State.

Sub: Violation of provisions of MCDR, 2017 in respect of Sangamkalan Limestone Mine-II over an area of 131.70 ha in Sangamkalan Village, Tandur Mandal, Vikarabad District, Telangana State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 17.09.2021 by the undersigned accompanied by Sri T.Mallikarjun Reddy, Mines Manager.

| Rule No- | Nature of violation |
|----------|---|
| 11 (1) | No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section(2) of section 5. (a) It was proposed to develop the Mine by maintaining a Bench Height of 8 meters. However, during the inspection it was observed that on the Eastern side of the working pit the bench height is more than the proposed height. (b) Further, two benches have been merged on the Northeast corner of the working pit and made more than 8 meters height. (c) The bund height on either side of the haul road is less than 1 meter of height.. |
| 31(1) | Every plan or section prepared or submitted in accordance with the provisions of the MCDR,2017. “In the surface Plan all the features have not been marked. An updated Surface Plan to be submitted.” |
| 40 | Every holder of prospecting licence or a mining lease shall take all possible measure to keep air pollution due to fines, dust, smoke or gaseous emissions during prospecting, mining, beneficiation or metallurgical operations and related activities within permissible limits. “ During the inspection of the Mines it was observed that no measures for dust suppression were undertaken”. |

02. In this connection, it is brought to your notice that the above said violations constitute an offence punishable under Rule-62 of MCDR, 2017. Further, inability to comply the provision of Rule 11(1) is liable for suspension of mining operations under Rule 11(2) of MCDR,2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully
Sd/-

(Shailendra Kumar)
Regional Controller of Mines

मूल प्रति पर नहीं/Not on the Original :

- 1) खान नियंत्रक (द), भारतीय खान ब्यूरो, बैंगलोर को प्रतिलिपि सूचनार्थ अग्रेषित।
- 2) The Director, Department of Mines & Geology, Govt. of Telangana, II floor, My Home Sarovar Plaza, Adarsh Nagar, Hyderabad-500063.
- 3) The ADMG, Govt. of TS, opp Vinayaka Temple, Pathakunta, Adarsh Nagar, Saipur, Tandur Town, Vikarabad-501141.

Sd/-
(Shailendra Kumar)
Regional Controller of Mines

