

## भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



File No: MP/SIDHI/LST-08 4657 - 4661

Scheme No.-11, Kamla Nehru Nagar Jabalpur, Dated: 29 / 04 /2021

To.

- 1) Shree K.C. Jhanwar (Nominated Owner) B- wing, Ahura Centre, 2nd Floor, Mahakali Caves Road Andheri East, Mumbai- 400093
- 2) M/S Ultra Tech Cement Ltd. Aditva Vihar, P.O.- Bharatpur Tehsil-Rampur Naikin Distt-Sidhi (M.P.)- 486776

Subject: - Violation of provisions of Mineral Conservation & Development Rules, 2017, in respect of your Budgauna Extension Limestone Mines (area-87.992 Hect.) in District of Sidhi in M.P. State.

Dear Sir.

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during MCDR inspection on 12.01.2021 by the undersigned in presence of Shree Mukesh Kumar Thawait.

Rule 11(1) **MCDR** 2017

- 1. Mining operations under mining lease.-(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.
- (2) If the mining operations are not carried out in accordance with the approved or certified mining plan or any information contained in the mining plan is found to be incorrect, misleading or noncompliant with applicable laws including these rules, the competent authority may by order, suspend all or any of the mining operations and permit continuance of only such operations as are required to restore the conditions in the mine as envisaged under the approved or certified mining plan or modified mining plan, for the purpose of restoration to the extent possible:

During inspection for the year 2019-20, it is observed,

- (1) Only 05 nos. of boreholes are drilled against proposal of 07 nos. during 2019-20.
- (2) Development and production are very less than planned -

Material	Planned	Achieved
Topsoil	8407 M <sup>3</sup>	2500 M <sup>3</sup>
ОВ	84779 M <sup>3</sup>	23000 M <sup>3</sup>
Limestone	600011	30135

(3) Garland/Toe fund was not maintained in all around the waste dump. Thus, there is violation of this rule.

02.In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.

03 . You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय.

Ole.

भारतीय खान ब्यूरो

NOO:

प्रतिलिपि प्रेषित : :

01. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal(M.P.) for information and further necessary action.

02. The District Collector, Sidhi (M.P.) for information.

OLC

उप खान नियंत्रक भारतीय खान ब्यूशो

प्रतिलिपि प्रेषित :

खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर को सूचनार्थ प्रेषित।

olc

भारतीय खान ब्यूरी

पता : योजनाकमांक 11, कमलानेहरू नगर, जबलपुर 482002 (मठप्र०) / फोन2416780 / 2416589 / 2416231 फैक्स0761- 2416780 Address : Scheme No 11, Kamla Nehru Nagar, Jabalpur 482002 (M.P) Phone 2416780 / 2416589 241631 Fax : (0761) 2416780 E Mail : ro.jabalpur@ibm.gov.in

25