भारत सरकार खान मंत्रालय भारतीय खान ब्यूरो क्षेत्रीय खान नियंत्रक का कार्यालय

फाईल सं.: ORI/IRON-MN/KJR/MCDR-84/BBS

्र Mine Code-30ORI08013 दिः 28/09/2018

सेवा में.

General Manager,

Raw Material Division

Steel Authority Of India Limited

Bolani Iron ore Mines, Post-Bolani-758037

Dist- Keonjhar-758035, Odisha.

.Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your in respect of your Bolani Ores Mines, over an area of 1321.45 hectare in Keonjhar District.

Sir.

The following provisions of MCDR,2017 were found violated in your above mine during inspection on 19/09/2018 by undersigned and Shri S. R. Mazumdar, SMG, in presence of Shri Ravi Ranjan,

AGM (Mines).

Rule No.	Nature of violations observed
13(2)	The benches in overburden shall be kept sufficiently in advance so that their workings do not interfere with the working of ore. However it has been observed that in 'D area pit' the benches are not sufficiently in advance. The width of top benches maintained 4-5m against the proposal of 7m width.

- 02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office Doyanand y within 45 (forty-five) days from the date of issue of this letter.

(D. Upadhyay)

Senior Assistant Controller of Mines Indian Bureau of Mines

Copy forwarded to:

- 1. The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.
- 2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Building / New Capital / Bhubaneswar-751 001.

Senior Assistant Controller of Mines Indian Bureau of Mines

of the second