भारत सरकार खान मंत्रालय भारतीय खान ब्यूरो

क्षेत्रीय खान नियंत्रक का कार्यालय

फाईल सं: ORI/MN/KJR/MCDR-21/BBS

Mine Code-40ORI08033 दिः 28/09/2018

सेवा में,

Amit Dubey

Agent & Head Manganese Group of Mines

M/s Tata Steel Limited, FA & MD

At & Po: Bichhakundi, Via- Joda, Dist-Keonjhar-758034, Odisha.

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your in respect of your Tiringpahar Manganese Mines over an area of 643.710 hectare in Keonjhar District.

The following provisions of MCDR,2017 were found violated in your above mine during inspection on 18/09/2018 by undersigned along with Shri S. R. Mazumdar, SMG, in presence of yourself

& Shri Niranian Kumar Mines Manager.

& Shri	Niranjan Kumar, Mines Manager.
Rule No.	Nature of violations observed
11(1)	Mining operations have not been carried out in accordance to Scheme of Mining, approved vide this office letter number MS/OTFM/34-ORI/BHU/2014-15, dated 29.04.2015 to the extent given below: 1) In 2017-18, total 20 nos. of bore holes was proposed but it was observed during inspection that the proposed location (11200N/11500N & 11750E/11900E) of 10 nos. of bore holes drilled during the year other than the proposed location in eastern part. 2) In 2017-18, it was proposed to excavate the 217848 cu.m. OB and 24706 T of ore from Gurda Block-B but it has been observed that no development and ROM production has been carried from
	this Block. Mining operation shall be such that different grades of ore can be obtained simultaneously for Hayayayar it has been observed that Gurda
13(3)	blending with a view to achieve optimum recovery of ore. However it has been desired and ROM has not been produced as proposed which resulting in hindrance of the interest of mineral conservation and optimum
	recovery of ore

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Senior Assistant Controller of Mines oll Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.

1. The Controller of Mines (EZ) / Indian Bureau of Mines / Rolland.

2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Orista / Department Origina / Department / Depa Building / New Capital / Bhubaneswar-751 001. (D. Upadhyay)

in Nigo

Senior Assistant Controller of Mines Indian Bureau of Mines