



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय  
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं/No.: KNT/BLR/Fe-397/BNG Mine-code: 30KAR03092

दिनांक/Dated: 11/10/2021

To,  
Shri Sanjeev Sahi,  
Chief General Manager /Agent-Mines  
M/s NMDC Limited,  
P.O.Donimalai Township,  
Bellary Dist, Karnataka-583118

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Kumaraswami Iron ore Mine, ML 1111 over an extent of 647.50 ha, in Kammathuru Village, Sandur Taluk , Bellari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 25.09.2021 by the undersigned along with Shri K. Srinivas, AMG in presence of Shri Dhiren Bhushan, DGM(Min), Shri.R.K.Tekam, DGM(Min), Excavation In-charge, Shri D.Somasekhara Reddy, DGM(Geo)/HOD (Geology), Dr. D.N.Subramanyam, Mine Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	Modified Mining plan was approved by IBM vide letter no. 279/290/91/BNG/927dated 13/12/2019, for the period 2020-21 to 2021-22. The deviations observed in mining operation vis-à-vis approved document are given below. During the field inspection it was observed that a new OB dump in location N-76572 to N-76766 & E-76265to E-76714 were developed in C Block which was not proposed in the modified mining plan.
24	The holder of a mining lease shall submit a final mine closure plan to the competent authority for approval two years prior to the proposed closure of the mine as the mining Lease deed is valid upto 17.10.2022 & no further extension letter has been received in this office from Department of Mines & Geology, Government of Karnataka.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Arun Kumar)

Deputy Controller of Mines  
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Arun Kumar)

Deputy Controller of Mines  
Indian Bureau of Mines