



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 /
23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KNT/BLR/Fe-403- Vol-II

दिनांक/Date: 12/10/2021

सेवामें/To,
Sri. Faisal Shareef,
Managing Partner,
M/s. Nadeem Minerals,
53, Empire Tower, 3rd Floor, Railway Parallel Road,
Kumara Park West, Bengaluru-560 120.

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Donimalai Iron Ore Mine (ML No. 2526)** over an area of **52.82 Ha** (as per CEC) in Taranagar village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Shri. H.M.Shivakumar-Assistant Mining Engineer in presence of Shri. Vuppu Lowa Raju- Manager (Mines), Shri Amarayya Patri-Mining Engineer & Shri. Venkata Subbaiah -Geologist on **27/09/2021**.

| Rule | Nature of violations observed |
|--------|--|
| 11 (1) | Modified RMP along with PMCP was approved vide letter No. 279/591/97/BNG dated 24/06/2020 for the period 2020-21. The deviations observed in mining operations vis-a-vis approved document are given below: It was proposed to maintain 8m bench height and bench width more than the height. During the inspection it was observed that at some places between the working sections 6-6' & 7-7' the width of the benches are lesser than the approved height. |
| 26(2) | A yearly report as per the format specified by the Indian Bureau of Mines has not been submitted before 1 st July 2021 setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan. |

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

सं/No.: KNT/BLR/Fe-403 Vol-II

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(वी. जयाकृष्णा बाबू / V.Jayakrishna Babu)
क्षेत्रीय खान नियंत्रक/Regional Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining &Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001.

Sd/-

क्षेत्रीय खान नियंत्रक/Regional Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines