

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
Office of the Regional Controller of Mines, Hyderabad

No. AP/KNL/Lst-7/HYD

Room No.603, 6th Floor,
CGO Towers, Kavadiguda,
Secunderabad.-500080.
Date: 30.09.2016

To

Sri L. Abdul Rehman Khan,
Managing Director,
M/s Deccan limestone Mining Co.(P) Ltd.,
Dhone (At & Po), District.

Sub: Violation of provisions of Mineral Conservation and Development Rules, 1988 (MCDR, 1988) in respect of Mothugapoda Limestone Mine of M/s Deccan limestone Mining Co.(P) Ltd., over an extent of 18.61 ha in Madhavaram R.F. ,Peapully Mandal, Kurnool district of Andhra Pradesh State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above mine during inspection on 15.09.2016 by Smt. Ch. Suseela, Assistant Mining Geologist, accompanied by Sri V.Samuel, Mines Manager of your mine.

Rule No.	RULE POSITION	NATURE OF VIOLATION
13(1)	Every holder of a mining lease shall carry out mining operations in accordance with the approved mining plan with such conditions as may have been prescribed under sub-rule (2) of rule 9 or with such modifications, if any, as permitted under rule 10 or the mining plan or scheme approved under rule 11 or 12 as the case may be.	I. During the inspection it was observed that the excavation is being carried out in two pits as against the approved proposal in one pit. II. The quantity of 21520 tonnes of waste is proposed to be generated during the year 2015-16 against which no waste was generated. It seems that there is 100% recovery of Limestone as against the proposal of 88%. III. There is a proposal of plantation of 1000 saplings in 7.5m safety barrier zone during the year 2015-16; against which no plantation was carried out.
23 E (2)	The owner, agent, manager or mining engineer shall submit to the Regional Controller of Mines or the officer authorised by the State Government in this behalf, as the case may be, a yearly report before 1 st July of every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof.	The yearly report for the year 2015-16 setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved scheme of Mining has not been submitted to the Regional Controller of Mines, Indian Bureau of Mines, Hyderabad.
27(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (b) of sub-rule (1) of rule 42, and within twelve months in the case of any other mine-	During inspection it was observed that plans and sections required under these rules have not been maintained updated.

02. In this connection, it is brought to your notice that the above said violations constitute an offence punishable under Rule-58 of MCDR, 1988. Besides, inability to comply the provision of Rule 13(1) is liable for suspension of mining operations under the provision of Rule 13(2) of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(IBRAHIM SHARIEF)
Sr. Assistant Controller of Mines

मूल प्रति पर नहीं/Not on the Original:

1. खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलुरु को प्रतिलिपि सूचनार्थ अग्रेषित ।
2. Copy for information & further necessary action to the Director of Mines and Geology, Government of Andhra Pradesh State, Hyderabad.
3. The Assistant Director, Dept. of Mines and Geology, Govt. of Andhra Pradesh, Kurnool district, A.P.

(IBRAHIM SHARIEF)
Sr. Assistant Controller of Mines