

भारत सरकार/Government of India खान मंत्रालय/Ministry of Mines भारतीय खान ब्यूरो/Indian Bureau of Mines नागपुर क्षेत्रीय कार्यालय/Nagpur Regional Office

By Speed Post/Email

छटवी मंजील, बी एव सी ब्लाक, इंदीरा भवन, सिविल लाइन्स, नागपुर-44001 6th Floor, 'B' & ''C' Block Indiira Bhawan, Civil Lines, Nagpur-440001 दुरभाष / Telephone- 562794 2565089 (Tel/Fax) इमेल-rcom.nr@ibm.gov.in

Date: 22.07.2021

No. MAH/YTL/LST-DOL-56/NGP-Vol.II

To.

Smt Deepali Gopal Gundawar, Plot NO. 3, Orchid Bloom Apartment, Laxmi VIhar, Sainagar, Wardha Road, Somalwada, Nagpur, Maharashtra - 440025

Sub:-

Violation of provision of Mineral Conservation and Development Rule 2017 in respect of Smt. Deepali Gopal Gundawar Limestone & Dolomite Mine Mine Code 38MSH26030 over an area of 30.00 Hectares situated near village Adegaon District-Yavatmal of Maharashtra State

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 14.07.2021, by the undersigned along with Shri. Deepak Chinchkhede, Assistant Mining Engineer

Rule

Nature of Violation observed

- 11(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part-B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016. The following deviations were observed in the approved Mining Plan dated 19.11.2018.
 - 1. It was proposed to work in Pit no. 1 as per grid reference N-2191750 to N-2191465 & E-286460 to E-280685 but it is observed that work was done as per grid reference N-2191485 to 2191780 & E-280460 to E-280460. Similarly in Pit no. 2 it was proposed to work in between N-2191945 to N-2191855 & E-280940 to E-280790, but it is observed that work was done in between N-2191750 to 2191965 & E-280855 to E-281160.

- 2. It was proposed to stack limestone in the pit no 2, but it is observed that there are number of limestone stacks in the North & Eastern side of the lease area.
- 47 The holder of a mining lease shall send an intimation in Form I of the Schedule to the authorized office as the case may be within fifteen days after the commencement of the borehole to a depth exceeding ten meters from the surface:-

As per this office records, it is observed that, you have not submitted the Notice of Sinking of Borehole in Form-I to this office.

1. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

2. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.

3. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,

Regional Controller of Mines

Copy to.

1. The Director, Directorate of Geology & Mining, Government of Maharashtra, Khanij Bhwan, 27-Shivaji Nagar, Cement Road, Nagpur-440010 (MS).

2. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur.

Regional Controller of Mines