

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
Mine Code-11ORI19013

फाईल सं.: ORI/CR/JJP/MCDR-13/BBS / 1991

दि: 02.11.2016

सेवा में,

Director & Nominated Owner,
M/s Balasore Alloys Ltd.
Module C/1, 1st Floor,
Fortune Tower, Chandrasekharpur,
Bhubaneswar, -751023.

Sub: Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect of your **Kaliapani Chromite mine**, over an extent of 64.463 hectare in Jajpur District.

Sir,

The following provisions of MCDR, 1988 were found violated in your above mine during inspection on **29/09/2016** by undersigned in presence of Mine officials Sri Prem Prakash GM, Geology, Sri Amarnath Dhar, Mine Manager and Sri P.K. mahapatra, Mining Engineer.

Rule No.	Nature of violations observed
13(1)	Mining operations have not been carried out in accordance to Scheme of Mining, approved vide this office letter number MS/FM/27-ORI/BHU/2014-15 dated 27.03.2015 to the extent given below: 1) Mining operation was proposed to carry out by forming 8m bench height 8-10m bench width. While during inspection it has been observed that in North-western part of pit bench height & width has been found less than 8m. 2) Southern part of the waste dump no.-2 has been extended beyond the proposed site. 3) Towards eastern part of waste no.-2 & mineral rejects a retaining wall has been proposed but during inspection it is observed that proposed retaining wall has not been made at the proposed site. 4) Since 2015-16, mining operation was proposed by regular opencast method and Underground mining method but it is observed that Underground mining has not been started till date of inspection.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of Mineral Conservation and Development Rules, 1988.
03. The mining operations can be suspended under rule 13(2), if compliance of rule 13(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

ok
Dayanand Upadhyay
02.11.16
(D. Upadhyay)
Assistant Controller of Mines
Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (CZ) / Indian Bureau of Mines / Nagpur-440 102.
2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Building / New Capital / Bhubaneswar-751 00.

ok
Dayanand Upadhyay
02.11.16
(D. Upadhyay)
Assistant Controller of Mines
Indian Bureau of Mines

15/11/16
2.11.16