



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो, क्षेत्रीय कार्यालय रायपुर

दूसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र

महालेखाकार आफिस कोम्प्लेक्स, पोस्ट -विधान सभा- रायपुर- (छ.ग)-492005

फोन- 0771--2282530/2285590/95 [मेल- ro.raipur@ibm.gov.in](mailto:ro.raipur@ibm.gov.in)

No- CHG/KNK/FE-6/NGP

दिनांक -16/11/2021

प्रेषिति- श्री श्रवण कुमार गोयल, नामित मालिक,
 I oUll बजरंग पावर एवम इस्पात लिमिटेड,
 ग्राम-बोरझरा, उरला-गुमा,
 उरला गोथ सेंटर, रायपुर(छ.ग.)-493221
 Email: mining@goelgroup.co.in

विषय- छत्तीसगढ़ राज्य के कांकेर जिले मे स्थित आपकी हाहल्दी लौह आएस्क खदान 75.00 हे. मे खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध मे-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 26.10.2021 by undersigned accompanied by Shri D.K.Mahanta, Agent(Mines).

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the approved Mining Plan. The Review of Mining Plan was approved vide letter no. कांकेर / लौह /खयो-1191/2018-रायपुर dated 28.02.2019 and following deviation was observed during inspection 1. The mining operation is not carried out as per proposal and as per proposal the bench height is be maintain 6 meter but during mine visit it was observed that in many benches height and width not maintained as per proposal and benches has collapsed and merged 3 benches. 2. During mine visit it was observed that Iron ore boulders are scattered in mine benches and some places boulders has been kept at the edge of mine benches which is against the systematic and scientific development.
37(1)	The existing protective measures taken around waste dump are insufficient and it has been found that the waste material was escaping and washing away from the dumps and was contaminating the nearby area and extending proposed area near road side and no retaining wall constructed. A proper protective measure should be taken to prevent the escape of the material from the existing waste dumps.

- 2 इस संदर्भ मे आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नही होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
 (क) खान की सारी खनन संक्रियाएं बंद की जा सकती है।
 (ख) आपके विरुध अभियोग दायर किया जा सकता है।
 (ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे।

भवदीय

(राजेश कुमार दास)

वरिष्ठ सहायक खान नियंत्रक

भारतीय खान ब्यूरो, रायपुर

