

VIOLATION LETTER
रजिस्टर्ड एंटीडो

संख्या : एचपी/एसआरएम/एलएसटी-14 Mine Code:38HPR10024

100-ओल्ड नेहरू कालोनी,
देहरादून, (उत्तराखण्ड),
दिनांक : 07.10.2016

सेवा में : श्री वी० के० वालिया
ग्राम व पोस्ट - ददाहू
तहसील- रेनुका,
जिला- सिरमौर (हि० प्र०)

विषय : Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect Of your Sangrah Bortli Limestone Mine located in Sirmour District of Himachal Pradesh State.
महोदय,

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection made on 22.09.2016 by the undersigned in presence of Shri D.K.Sinha, Mine Manager

Rule No Nature of violation observed in detail

- 13(1):** The mining operations are carried out in violation of following provisions of approved Modified Mining (approved on 07/09/2012): -
(i) Proposed exploration work has not been carried out as envisaged in the approved mining plan.
(ii) Mine development work is not commensurate with the proposal made in the approved modified mining plan.
- 25** The owner, agent, mining engineer or manager of every mine shall send to Controller General, Controller of mines and the Regional Controller of mines an intimation in Form C of reopening of a mine after temporary discontinuance, so as to reach then within fifteen date from the such reopening.
But you have not sent such intimation in Form C after reopening of your mine.
- 02.** In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.
- 03.** The mining operation can be suspended under rule 13(2) of MCDR 1988 if compliance of rule 13(1) of MCDR 1988 is not found satisfactory.
- 04.** You are advised to rectify the above violations immediately and intimate the position to this office on letter pad signed by the owner within 45 (forty-five) days from the date of issue of this letter.

भारतीय,
बचत निधि
(डी० आर० गुर्जर)
सहायक खान नियंत्रक
भारतीय खान ब्यूरो

etc

प्रतिलिपि सूचनार्थ-

1. खान नियंत्रक (उ०), भारतीय खान ब्यूरो, अजमेर।
2. निदेशक, उद्योग विभाग, उद्योग भवन, हि०प्र० सरकार, शिमला।

दि० ०७/१०/१६ etc