

भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय /MINISTRY OF MINES

भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक का कार्यालय /OFFICE OF THE REGIONAL CONTROLLER OF MINES No. ORI/CR/JJP/MCDR-4/BBS/VoL-III / 26 8

Plot No. 149, Pokhariput Bhubaneswar - 751 020 Date: 05.05.2016

To

Shri Rohit Saraf, Nominated Owner, Ferroy Alloys Corporation Ltd, Laxmi Bhawan, Kuans, Bhadrak, Odisha - 756100

Sub: Violation of provisions of MCDR, 1988 in respect of your Ostpal Chromite Mine over an area of 72.843 ha in Jajpur district of Odisha State.

Sir,

The following provision of Mineral Conservation and Development Rules, 1988 (MCDR, 1988) were found violated in the above mine during inspection on 13.03.2016, by Shri Ibrahim Sharief, Assistant Controller of Mines and co

Totalini Sharet, Assistant C	ontroller of Mines and communicated to you on the spot.
Rule No.	Violation
13(1):- Every holder of a	of I make a sum of the first the fir
mining lease shall carry	approved depth of 50 mRI, for the year 2015-16
out mining operations in	(ii) Bench height is found to be 10-12 m against the approved
accordance with the	The second of the second to the inglier than height at
approved mining plan	The state of the s
with such conditions as	by the state of th
may have been prescribed	and the state of t
under sub-rule (2) of rule 9 or with such	Ti T
	waste material.
permitted under rule 10 or	(iv) Garland drain all along bottom periphery of waste dump in
the mining plan or scheme	south dump yard has not been maintained as per approved
0 1	proposal.
12 as the case may be.	(v) Stabilization of un-used waste dump has not been carried out
12 as the case may be.	by plantation.
	(vi) ROM ore generated is not being weighed, only it is observed
	that the fines (which are to be dispatched) as well as material
15(5)()()	feed to COB plant is being carried out.
45(5)(a)(iv): A monthly	On examination of monthly return submitted for the month of
return which shall be	February 2016, the following discrepancies is observed:-
submitted before the 10th	In part II, item 2(ii) total ore dispatch from mine head (including
of every month in respect	concentrate) is furnished as 15093.62 MT, but in para II, item 4,
of preceding month.	the total quantity dispatch is furnished as 7303.4 MT.



45(5)(b)(iv): An annual return which shall be submitted before the 1st July each year for the preceding year.

On scrutiny of annual return submitted for the year 2014-15, the following discrepancies is observed:-

(i) In part VI, item 2(ii), total ore dispatch from mine head (including concentrate) is furnished as 212214.63 MT, whereas in part VI, item 4, total quantity dispatch effected for domestic consumption is furnished as 99514.06 MT.

(ii) In part VII, cost of production per MT is furnished as Rs. 4677.85 and in part VI, item 4, ore is consumed to be for captive purpose, whereas in part VI, item 2 (ii), Ex-mine price for ore of below 40% Cr2O3 is furnished as Rs. 3352.90 and for ore of 40% to below 52% Cr2O3 is furnished as Rs. 8845.31.

As per rule, for captive consumption of ore, Ex-mine price for ore should be cost of production/MT of ore.

In this connection, no reply about compliance of above violation has yet been received from you. In this regard, it is also brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988. The relevant extract of the rule 58 is given below:

- "58 Penalty: Whoever contravenes any of the provisions of these rules shall be punishable with imprisonment for a term which may extend up to two years, or with fine extending to fifty thousand rupees or with both, and in the case of continuing contravention with an additional fine which may extend up to five thousand rupees for every day during which such contravention continues, after conviction for the first such contravention, provided that for repeated contravention the punishment should be in the form of imprisonment only".
- 3. You are therefore directed to show cause within a period of 30 (thirty) days from the date of issue of this letter as to why you should not be prosecuted for the above offence and/or the mining operations shall not be suspended under Rule 13 (2) of MCDR, 1988, till the rectification of the violations.
- 4. Please note that no further notice will be given to you in this regard.

orc

Yours faithfully,

(M BISWAS)

Regional Controller of Mines

प्रतिलिपि निम्न को सादर सूचनार्थ / Copy forwarded for kind information to:

(1) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टरेट ऑफ माइन्स / Directorate of Mines, ओड़ीशा सरकार /Government of Odisha, हेड्स ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर/Bhubaneswar-751 001

(2) खान नियंत्रक;मध्यांचलद्ध/ The Controller of Mines (CZ), भारतीय खान ब्यूरो/ Indian Bureau of Mines, नागपुर /Nagpur-440 102.

ore

(MJBISWAS)

Regional Controller of Mines