

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय

स्पीड पोस्ट

संख्या : 614(2)/एमएस-बी-3/95-डीडीएन.

100, ओल्ड नेहरू कालोनी,  
देहरादून (उत्तराखण्ड),  
दिनांक : 01.04.2016

सेवा में :  
मै0 जे0एस0ठाकुर एण्ड संस,  
119/10 देवीनगर,  
पावंटासाहिब,  
सिरमौर (हिमाचल प्रदेश)

विषय : मै0 जे0एस0ठाकुर एण्ड संस की जिला -सिरमौर (हिमाचल प्रदेश) स्थित बलधवा लाइमस्टोन खान की ड्राफ्ट स्कीम आफ माइनिंग।

सन्दर्भ : आपका पत्र संख्या-शून्य दि0-20.02.2016  
इस कार्यालय का पत्र संख्या सम दि0 25.02.2016  
महोदय,

उपरोक्त ड्राफ्ट स्कीम आफ माइनिंग इस कार्यालय में दो प्रतियों में दि. 23.02.2016 को प्राप्त हुई है। खान का निरीक्षण श्री डी0 आर0 गुर्जर, सहायक खान नियंत्रक द्वारा दि0 12.03.2016 को किया गया। निरीक्षण एवं ड्राफ्ट स्कीम आफ माइनिंग के अवलोकन के पश्चात पाई गई कमियों का ब्योरा अनुलग्नक में दिया गया है।

अतः आपको सलाह दी जाती है कि आप अनुलग्नक में दर्शाई गई सभी कमियों को दूर कर उचित दस्तावेज तीन प्रतियों में साफ्ट कॉपी (सीडी) के साथ इस कार्यालय में पत्र के जारी होने के 30 दिन के अन्दर प्रस्तुत करें ताकि आगे की कार्यवाही की जा सके। निर्धारित 30 दिन में उचित दस्तावेज सभी कमियों को दूर करते हुए प्रस्तुत नहीं करने की स्थिति में इस पर अन्तिम कार्यवाही कर दी जायेगी। ड्राफ्ट स्कीम आफ माइनिंग जो इस पत्र के साथ संलग्न कर आपको भेजी जा रही है, जिसको भी फाइनल उचित दस्तावेज की तीन प्रतियों के साथ प्रस्तुत करें।

संलग्न : एक प्रति.

भवदीय  
o/c  
(कै0 एस0 यादव)  
क्षेत्रीय खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ-

1- खान नियंत्रक (उ०), भारतीय खान ब्यूरो, अजमेर।

2 मै0 उदयपुर मिन-टेक प्रा0 लि0, 206, अपेक्षा कॉम्प्लेक्स, सेक्टर-11, हिरन मगरी, उदयपुर-313  
001(राजस्थान) को इस पत्र के साथ ड्राफ्ट स्कीम आफ माइनिंग की एक प्रति भी संलग्न की जा रही है।  
(स्पीड पोस्ट)

विद्यारी c.l.l D:\desktop dated 01-07-2014\DRG\Hindi Fo.Scr.MS. Balidhwa JST KSY.doc

पत्र प्रेषित किया  
दि० ०१/०४/१६

o/c  
क्षेत्रीय खान नियंत्रक  
भारतीय खान ब्यूरो



Scrutiny comments in respect of Scheme of Mining of Baldhawa Limestone Mine of M/s J.S. Thakur & Sons (12.38 Hectares) in District Sirmour, Himachal Pradesh State submitted under rule 12 and 23(B) of MCDR 1988.

1. On the cover page information about lease period in light of MMDR Act 2015 has not been given.
2. The lease area mentioned on the cover page as well as in the text is 12.38 Ha while in the in the list of mines provided by State Govt it is 12.2Hect. The conversation from Bigha to Hectare as per Norms of Revenue department of HP is to be mentioned and should be certified by Geology & Mining Department. All these details should be enclosed in the introductory chapter.
3. Authentic lease plan by Mining department of State Govt showing the location of the lease area by red colour should be enclosed. Authentic lease plan shall be the basis for the preparation of all the plans and sections. There should not be any deviations in all the plans and sections with respect to configuration given in the lease plan.
4. Under introduction chapter on page no. 2 it is mentioned that no other mining leases held by the lessee while Bohar Limestone mine in Sirmour District of HP state falls under the Jurisdiction of this office.
5. There are three key persons of RQP certificate RQP/UDP/354/2009-B but the signature of two key persons in the document. As per Mineral Concession Rule 2016 there are no provisions of RQP.
6. Under chapter 3.0 Details of approved mining plan/scheme of mining there are 06 bore holes were proposed in the last SOM period but same exploratory holes has not been drilled and also not been proposed during the next SOM period.
7. In part A chapter 1.0 Geology & Exploration on page no. 18 the resource between 1756mRL to 1600mRL is considered under G1 category (331) and below that 10m considered under G2 category. What is the basis of that consideration?
8. In part A Chapter 2.0 Mining chapter on page no. 28 it is assumed 10% of ROM is mineral reject while in the year wise calculation of production tables it is not shown. Saleable quantity of mineral and mineral reject should also be bifurcated in the year wise production table on page no. 30 to 34.
9. Generation of 10% ROM as mineral reject is quite high in such homogeneous mineral deposit. Its analysis is to be submitted; necessary arrangements should be made for its separate stacking for mineral conservation.
10. In plate no. 3B & 3D section along JJ' is not matching with plan.
11. As per sections shown in plate no. 3A to 3E; vertical escarpments shown; suitable proposal should be incorporated in the next five years to reduce bench heights on the priority basis.
12. In part A Chapter 2.0 Mining on page no. 37 under present land use pattern the backfilling shown 3.074 Ha while at the end of SOM period it is 1.974 it needs to be rechecked. Figures given on page no.64 are also not matching.

13. In PMCP chapter on page no. 63 the year wise community development has been given only for the next two year i.e. 2016-17 & 2017-18. Proposal for remaining three year of SOM period should also be given.
14. The proposed waste dumping for the next five years shown along 'Kalhon Ka Khala'; suitable protective measures should be incorporated to roll down the waste along the nalla.
15. The validity of current bank guarantee is up to 22-11-2016, so bank guarantee for the next SOM period shall be submitted at the time of fair copies submission.
16. Place & Date has not mentioned on Consent letter/Undertaking/Certificate from lessee as enclosed in Part B.
17. Feasibility report has not been enclosed.
18. All the annexure should be attested by RQP for their authenticity.
19. There are several typographical mistakes, which require to be corrected. All the corrections made by pencil and pen in the draft copy should also be attend during the preparation of final copies.
20. Additional comments shall also be communicated to you in case of receipt of comments from State government if any.
21. A CD covering the entire document and plans should be enclosed at the time of final submission. An undertaking in this regards by the RQP that CD contains same documents & plates as submitted by hard copy of document & text should be given.

**Plates**

**22. Plate No. 3B & 3D**

Section along JJ' is not matching with plan.

**23. Plate No. 4(Reclamation Plan)**

Protective measures of waste dump along Nalla have not been mentioned in the index.

**24. Plate No. 7(Financial assurance Plan)**

Financial assurance Plan should be prepared as per guideline.