भारत सरकार /Government of India खान मंत्रालय/ Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/ Office of the Regional Controller of Mines

Phone No.: (0832) - 2741757 Opp. R.T.O.'s Office, Fax No. : (0832) -2741758 P.O. FATORDA - 403602,

E-Mail : <u>ro.goa@ibm.gov.in</u> Margao - GOA

GOA/FeMn/156 30GOA02087 Dated: 16/12/2016

To, Shri. Pramod P.Timblo, Legal Heir of Late Shri.Panduronga Timblo, Subhash Timblo Bhavan, Isidora Baptista Road, Post Box.No-242, Margao, Goa – 403 601

Sub: Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect of Borga Dongrachem Fall Mines, (TC-29/52) over an extent of 71.2014 Hectares situated in Rivona Village, Sanguem Taluk, South Goa District, Goa State – Reg.

Sir,

The following provision of Mineral Conservation & Development Rules, 1988 were found violated during the inspection of your above mine on 14.12.2016 by the undersigned.

13 (1)	 Mining operations in the lease area are not carried out as per the last approved Mining Plan. The following deviation is observed during inspection, a) It was observed during inspection that 2016-2017 production & development is being carried out in 2015-2016 proposed area. b) It was proposed in page-21, to drill 4 Boreholes during the Plan Period in the lease area, against which no exploration work has been taken up so far. c) It is proposed for restoration of collapsed benches by development quantity during 2015-2016, but no such activity has been carried out. d) As per page 40 of Modified Mining Plan, dispatch quantity was proposed from the stock yard in the year 2015-2016 but no such dispatch was carried out in this area.
23(E)(2)	An yearly report before 1 st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for last two years.
27(4)	The Plans & Sections required under rule 28 have not been submitted to this office.
63	A Self-Appraisal Report to be submitted by owner of the mine under Rule 63 of MCDR, 1988 stating extent of implementation of Approved Mining Plan/ Scheme of Mining during the year 2015 – 2016 along with supporting plans & sections representative photographs in hard as well as soft copy.

- 2. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 58 of MCDR, 1988.
- 3. The mining operations can be suspended under Rule 13(2), if compliance of rule 13(1) is not found satisfactory.
- 4. You are advised to rectify the violation immediately and intimate the position to this office with in a period of 45 (Forty Five) days from date of issue of this letter.

Yours faithfully,

(G.S.Kannan) Junior Mining Geologist

Copy forwarded for information to: -

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, DMG, Goa.
- 3. Mine File

(G.S.Kannan) Junior Mining Geologist