



भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
Office of Regional Controller of Mines



उल्लंघन पत्र

Jabalpur, dated: 14/02/2023

सेवा मे,

**Shri Neeraj Kumar Verma (Nominated Owner)**

M/s KJS Cement Limited  
Ground Floor, Unit No-005  
Copia Corporate, Jasola  
New Delhi-110044  
Email- [mines@kjscement.com](mailto:mines@kjscement.com)

विषय – म0प्र0 राज्य के Satna जिले में स्थित आपकी Bhatia Limestone Mine, (क्षेत्रफल- 10.431 हे0) में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन। (Mine Code-38MPR35098)

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by undersigned on 15.12.22 in presence of Shri Vijay Singh Rathore, VP (Mines), Shri Narayan Shukla, Geologist, Shri. Rajkumar, Mining Engineer and Rakesh K. Chaubey, Qualified Person detailed as below -:

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 11 (1)	<p><b><i>According to this rule-No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines;</i></b></p> <p>The Review of Mining Plan of above mentioned mine was approved vide this office letter No-MP/Satna/Limestone/RMP-74/2018-19 dated 25.04.2019 and following deviations/violations have been observed during mine inspection in accordance with approved proposals of ROMP-</p> <p>i) As per the para 1(i) of Geology &amp; exploration chapter, under the future exploration programme, total 03 core boreholes were proposed during the year 2019-20 &amp; 2020-21 but against to this proposal, no exploration carried out.</p> <p>ii) As per Para-2A of chapter-2, during the year 2021-22, development &amp; limestone production was proposed in Pit-1 between the grid pattern N2687470 to N2687715 and E489040 to E489215 from 327mRL to 314mRL. But during the year, development &amp; production not carried out as per the approved proposals and depth wards as well as later deviations were observed. Further, production of limestone also carried out in Pit-2 which was not proposed during the said year.</p> <p>iii) As per Para-2A of chapter-2, during the year 2021-22 total 7700 M<sup>3</sup> overburden/intercalated waste generation was proposed. But, against to this proposal, 258713 Tonnes (Considering tonnage conversion factor of 2.0/Tonne) of overburden/intercalated waste generation reported during the aforementioned year as per online annual return which is on higher side and are in contradiction with approved proposals.</p> <p>iv) As per Para-2A of chapter-4, during the year 2021-22, the total overburden material generated was proposed to be utilized for backfilling purpose over 7.5m excavated barrier zone towards North &amp; North-Eastern part of ML area. But no backfilling work carried as per the proposals.</p>
Rule 31(4)	<p><b><i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in case of any other mine</i></b></p> <p>As this is "A" category mine and required plans &amp; sections are need to be updated on quarterly basis as required under this rule but the same were are not being updated in stipulated time and not maintained at mines site office.</p>

Rule 54(a)	<p><i>The holder of a mining lease or a holder of a prospecting licence or prospecting license-cum-mining lease shall maintain the labour attendance register, production and dispatch register, royalty assessment register,—</i></p> <p>a) <i>Details of contribution made to District Mineral Foundation and National Mineral Exploration Trust; d) Details of mining machinery and copies of all notices and returns, plans, sections and schemes submitted to the authorised officer or the State Government or the Regional Controller under these rules,</i></p> <p>But, during mine inspection, it is noticed that you have not maintained relevant documents/records as required under the prescribed rule.</p>
------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The non-compliance of the rule 11(1) of MCDR, 2017 may lead to suspension of Mining operations under the provisions of rule 11(2) of MCDR, 2017.
04. You are therefore advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय,

**संजय म. गिरहे**  
क्षेत्रीय खनन भूविज्ञानी  
कृते क्षेत्रीय खान नियंत्रक

प्रतिलिपि सूचनार्थ हेतु प्रेषित :

1. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal (M.P.).
2. The District Collector, Satna (M.P.)- 485001
3. The Controller of Mines (CZ), IBM, Nagpur for information.

**संजय म. गिरहे**  
क्षेत्रीय खनन भूविज्ञानी  
कृते क्षेत्रीय खान नियंत्रक