

Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines, Jabalpur

File No.: MP/JBP/Lat-9(part-II)

Jabalpur, Dated: 30.06.2022

To,

**Shri. Nitin Sharma (Nominated Owner),**  
**M/s Shobha Minerals,**  
**765, Napier Town,**  
**Distt. - Jabalpur (M.P.) - 482001**  
**E-mail-shobhamineralsd@gmail.com.**

**Sub. :** Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your **Dhamki Laterite, Iron & Manganese Ore Mine** (3.60 hectare) Mine Code **75MPR18010** in District Jabalpur of M.P. State.

Sir,


Following provisions of MCDR 2017 were found violated in your above mine during the inspection by the Undersigned on **04/03/2022** in the presence of Shri Indraneel Dawande (Qualified person) & mines officials:

Rule No	Nature of violation observed in detail
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government. <ul style="list-style-type: none"><li>• Only 55001 tonnes ROM is produced against the proposal of 80044 tonnes for the year 2020-21.</li><li>• Only 1620 m<sup>3</sup> &amp; 1020 m<sup>3</sup> &amp; OB/waste is generated against the proposal of 10116 m<sup>3</sup> &amp; 11760 m<sup>3</sup> for the years 2020-21 &amp; 2021-22.</li><li>• The boundary pillars were not erected as per rule and in some places it was observed that pillars were erected after carrying out excavation of the said areas.</li><li>• A mineral dump of 0.2062 ha in the northwest portion and a waste dump of 0.17 ha in southwest portion of the lease between the grid-coordinates (2583960 to 2584005) N &amp; (401910 to 410960)E were observed which was not proposed during the years 2020-21 &amp; 2021-22.</li></ul>
34 A(3)	Every lessee shall carry out a drone survey of his leased area and upto hundred metres outside the lease boundary within six months before submission of any mining plan document or modification thereto to the Indian Bureau of Mines for approval and shall submit processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the concerned Regional Controller of Mines and the Controller General along with the application for approval of mining plan: <b>(DEM) and Orthomosaic images obtained from drone survey was not submitted during the application of the mining plan.</b>

1. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.
2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
3. You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

*o/c*


Yours faithfully

  
30/06/2022  
(Robert Simon C)  
Asst. Controller of Mines,  
Jabalpur Region, IBM

Copy to:

- 1) The Controller of Mines (CZ), IBM, Nagpur,
- 2) The Director, Directorate of Geology & Mining, Khanij Bhavan, Arera Hills, Bhopal (MP).

*o/c*

  
30/06/2022  
(Robert Simon C)  
Asst. Controller of Mines,  
Jabalpur Region, IBM