## INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

## Review and updation of Mining Plan REPORT

## Chennai regional office

	Mine file No : TN/MDR/LST-23.MDS					Mine code : 38TMN06022
	(i)	Name of the Inspectin Officer and ID No.	g :	<b>KØ8</b> )	G.SORNADURAI	KANNAN
	(ii)	Designation	:	Senior Mi	ning Geologis	st
	(iii)	Accompaning mine Official with Designation	:	Thiru. Ka	nnan, Lessee	Representative & Thiru N.Suresh
	(iv)	Date of Inspection	:	15/04/202	3	
	(v)	Prev.inspection date	:			
		P	ART-	I : GENI	ERAL INFORMAT	ION
1.	(a)	Mine Name	:	PANAMOOPP	ANPATTI LST	
	(b)	Registration NO.	:	IBM/18563	/2014	
	(c) (d) (e) (f) (g)	Category Type of Working Postal address State District Village Taluka Post office Pin Code FAX No. E-mail Phone Police Station First opening date		97904478	n@gmail.com 81 aickanur	
	(h)	Weekly day of rest	:	SUN		
2.		ess for espondance	:		VANDANPATTI F TI, MADURAI I	
3.	(c)	Lease Number Lease area Period of lease Date of Expiry	:	TMN1117 3.07 20 01/02/201	8	
4.	Mine	ral worked	:	LIMESTONE	:	Main

5. Name and Address of the

Lessee : B. THIRAVIYAM MADURAI TAMIL NADU Phone: FAX :

- Owner : B.THIRAVIAM 9/1,22 ATB ROAD, USILAMPATTI, MADURAI DISTRICT. MADURAI TAMIL NADU Phone: FAX :
- 6. Date of approval of Mining :
  Plan/Scheme of Mining

## PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	No Boreholes has been proposed during 2022- 2023.	No Boreholes has drilled	Mine is non- working from 2011- 2012.
1b	Exploration over lease area for geological axis 1 or 2	No Additional exploration boreholes was proposed over the lease area during 2022-2023	Nil	Entire lease area is proved upto 13m depth and under G- 1 category.
lc	Exploration Agencies and Expenditure in lakh rupees during the year	No Proposal for exploration during 2022- 2023	No Boreholes has been drilled	No Boreholes has been drilled during the plan period. (2018- 2023)
1d	Balance area to be explored to bring Geological axis in 1 or 2	Exploration was not proposed during 2022- 2023.	No Exploration has been carried out during 2022- 2023.	Entire area has been explored under G-1 category with 100m X 100m grid interval.
le	Balance reserve as on 01/04/20	As on 01.04.2023 Proved Mineral Reserves (111) = 1725 tons Pre- Feasibility Mineral Resources (221) = 11250 tons Measured Mineral Resources (331) = 81038 tons	As on 01.04.2023 Proved Mineral Reserves (111) = 12135 tons Pre-Feasibility Mineral Resources (221) = 11250 tons Measured Mineral Resources (331) = 81038 tons	It is proposed to use the entire 111 category ore for mining, but mine is not in operation for 2011-2012. The available grade of Limestone in this lease is cement Grade.
lf	General remarks of inspecting officers on geology, exploration etc	Area comprises Crystalline Archean rocks of deep seated metamorphic origin.	The deposit consists of Granite Gneiss, charnockites and Crystalline limestone.	Limestone is medium to coarse grained. Covered by 1m thick topsoil.

Development :

Sl.No. Item

Propasals Actual work

Remarks

2a	Location of development w.r.t.lease area	During 2022- 2023, working proposal was in Pit-2.	Nil	The mine is not in operation from 2011-2012.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Minerals - 1 Benches	Nil	The mine is not in operation from 2011-2012.
2c	Stripping ratio or ore to OB ratio	1 : 2.33	Nil	The mine is not in operation from 2011-2012.
2d	Quantity of topsoil generation in m3	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2011-2012.
2e	Quantity of overburden generation in m3	525 cu.m of mineral rejects Proposed during 2022- 2023	Nil	The mine is not in operation from 2011-2012.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	During 2022- 2023, working proposal was in Pit-2.	525 cu.m of mineral rejects Proposed during 2022-2023	The mine is not in operation from 2011-2012 for want of statuary clearance.

# Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	Production was Proposed in Pit-2	Nil	The mine is not in operation from 2011-2012.
3b	Quantity of ROM mineral production proposed	The total target of ROM Production proposed was 1875 tons during 2022- 2023.	Nil	The mine is not in operation from 2011-2012.
3c	Recovery of sailable/usable mineral from ROM production	30% Recovery-	Nil	The mine is not in operation from 2011-2012.
3d	Quantity of mineral reject generation	1313 tons of Mineral Rejects has proposed.	Nil	The mine is not in operation from 2011-2012.

3e	Grade of mineral rejects generation and threshold value declared.	High silica is considered as mineral rejects.	Nil	The mine is not in operation from 2011-2012.
3f	Quantity of sub grade mineral generation.	No Sub Grade Generation	Nil	The mine is not in operation from 2011-2012.
3g	Grade of sub grade mineral generation	There is No Generation of Subgrade Mineral	Nil	The mine is not in operation from 2011-2012.
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised method	Nil	The mine is not in operation from 2011-2012.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No Beneficiation Study is Proposed	Nil	The mine is not in operation from 2016-2017.
3j	Provision of drilling and blasting in mineral benches	Drilling & blasting are proposed	Nil	The mine is not in operation from 2016-2017.
3k	Provision of mining machineries in mineral benches	Tippers Drills Compressor	Nil	The mine is not in operation from 2011-2012.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	In 2022-2023, Bench height of 3m was proposed in Mineral.	Nil	The mine is not in operation from 2011-2012.
3m	Total area covered under excavation/pits	0.242 hect area is proposed for Pit during 2022-2023	0.05 hect areas are under Pit only.	The mine is not in operation from 2011-2012.
3n	Ore to OB ratio for the pit/mine during the year.	1 : 2.33	Nil	The mine is not in operation from 2011-2012.

30	Total area put in use under different heads at the end of year	Land use Pattern as on 01.04.2023. Mines = 0.242 hect OB Dump = 0.59 hect Mineral Reject Dump = 0.36 hect	Land use Pattern as on 01.04.2023. Mines = 0.05 hect	Due of non-working of mines, proposal is not achieved.
3p	Production of ROM mineral during the last five year period as applicable	2022-2023 = 1875 tons 2021-2022 = 2430 tons 2020-2021 = 2430 tons 2019-2020 = 1875 tons 2018-2019 = 1800 tons	2022-2023 = Nil 2021-2022 = Nil 2020-2021 = Nil 2019-2020 = Nil 2018-2019 = Nil	The mine is not in operation from 2011-2012 for want of statuary clearance.
3q	General remarks of inspecting officers on method of mining etc.	Production was Proposed in Pit-2.	The total target of ROM Production proposed was 1875 tons during 2022- 2023.	The mine is not in operation from 2011-2012 for want of statuary clearance.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Separate dumping has been proposed for OB & mineral reject during 2022- 2023	Nil	The mine is not in operation from 2011-2012.
4b	Location of topsoil, OB and mineral reject dumps	OB Dump proposed on Northern side and Mineral reject is proposed on Southern side of lease area.	Nil	The mine is not in operation from 2011-2012.
4c	Number of dumps within lease area and outside of lease area	Non Lease area	Lease area = Nil Non Lease area = Nil	The mine is not in operation from 2011-2012.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Outside UPL	Nil	The mine is not in operation from 2011-2012.

4e	Number of active and alive dumps.	—	Nil	The mine is not in operation from 2011-2012.
4f	Number of dead dumps.	No Proposal	Nil	The mine is not in operation from 2011-2012.
4g	Number of dumps established.	No Dumps have been established.	Nil	The mine is not in operation from 2011-2012.
4h	Whether Retaining wall or garland drain all along dumps are there.	No Proposal	Nil	The mine is not in operation from 2011-2012.
4i	Length of Retaining wall or garland drain all along dumps	No Proposal	Nil	The mine is not in operation from 2011-2012.
4j	Number of settling ponds	No Proposal	Nil	The mine is not in operation from 2011-2012.
4k	Specific comments of inspecting officer on waste dump management		OB Dump proposed on Northern side and Mineral reject is proposed on Southern side of lease area.	The mine is not in operation from 2011-2012 for want of statuary clearance.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal for backfilling during 2022- 2023	No backfilling has done during 2022-2023	The mine is not in operation from 2011-2012.
5b	Area under backfilling of mined out area	No Proposal	Nil	The mine is not in operation from 2011-2012.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No Proposal	Nil	The mine is not in operation from 2011-2012.
5d	Total area fully reclaimed and rehabilitated	No Proposal	Nil	The mine is not in operation from 2011-2012.

5e	General remarks	There is no	The mine was not worked	The mine is not in
	of inspecting	proposal for	upto the proved depth	operation from
	officers on	backfilling	and no backfilling were	2011-2012 for want
	backfilling and	during 2022-	proposed during 2022-	of statuary
	reclamation etc.	2023	2023.	clearance.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	It should be on or before 1st July every year.	Not Submitted	The mine is not in operation from 2011-2012.
6b	Area available for rehabilitation (ha) .	No Proposal	Nil	The mine is not in operation from 2011-2012.
бс	afforestation done (ha).	No Proposal	Nil	The mine is not in operation from 2011-2012.
6d	No. of saplings planted during the year	No Proposal	Nil	The mine is not in operation from 2011-2012.
бе	Cumulative no .of plants	No Proposal	Nil	The mine is not in operation from 2011-2012.
6f	Any other method of rehabilitation	No Proposal	Nil	The mine is not in operation from 2011-2012.
6g	Cost incurred on watch and care during the year	No Proposal	Nil	The mine is not in operation from 2011-2012.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	No Proposal	Nil	The mine is not in operation from 2011-2012.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No Proposal	Nil	The mine is not in operation from 2011-2012.

6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No Proposal	Nil	The mine is not in operation from 2011-2012.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No Proposal	Nil	The mine is not in operation from 2011-2012.
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No Proposal	Nil	The mine is not in operation from 2011-2012.
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	the safety barrier of	30 saplings have planted within lease area during 2022-2023.	Cumulatively 150 saplings has been planted from 2018- 2019 to 2022-2023.
бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	—	0.030 hect achieved in lease area for 2022-2023	The mine is not in operation from 2011-2012.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Green Belt development along 7.5m safety barrier.	Plantation has been done as per proposal along the safety barrier.	The mine is not in operation from 2011-2012.
бр	Compliance of environmental monitoring (core zone and buffer zone)	Bi-Annually Survey	Nil	The mine is not in operation from 2011-2012.
6q 	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	60 saplings proposed along the safety barrier of lease boundary for 2022-2023	Total 150 saplings has been planted from 2018- 2019 to 2022-2023.	The mine is not in operation from 2011-2012 for want of statuary clearance.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks	
7a	ROM Mineral dispatch or grade-wise sorting within lease area	The total target of ROM Production proposed was 1875 tons during 2022- 2023.	Nil	The mine is not in operation from 2011-2012.	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	There is no proposal for grade wise mineral sorting in the lease area.	Nil	The mine is not in operation from 2011-2012.	
7c	Different grade of mineral sorted out at mines.	The Limestone of the lease area is cement grade	Nil	The mine is not in operation from 2011-2012.	
7d	Any beneficiation process at mines	No Proposal	Nil	The mine is not in operation from 2011-2012.	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	The total target of ROM Production proposed was 1875 tons during 2022- 2023.	The Limestone of the lease area is cement grade	The mine is not in operation from 2011-2012 for statuary clearance.	

### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	during 2022-	Nil	The mine is not in operation from 2011-2012.
8b	Concurrent use or storage of topsoil	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2011-2012.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	dumping has been proposed for OB &	Nil	The mine is not in operation from 2011-2012.

8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal Nil for using OB, mineral rejects to restore the land to its original use during 2022- 2023		The mine is not in operation from 2011-2012.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No Proposal Nil		The mine is not in operation from 2011-2012.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	60 saplings proposed along the safety barrier of lease boundary for 2022-2023	30 saplings have planted within lease area during 2022-2023.	The mine is not in operation from 2011-2012.
8g	Survival rate	No Proposal in approved document	50%	The mine is not in operation from 2011-2012.
8h	Water sprinkling on roads to control airborne dust	Yes, it is proposed.	Nil	The mine is not in operation from 2011-2012.
81	General remarks of inspecting officer on aesthetic beauty in and around mines area	Scanty vegetation, bushes, neem are observed in lease area	Degraded Mining Land	Outside lease area, agriculture is done with drift irrigation.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Nil	Monthly & Annual Returns has not submitted for last 11 years.	The mine is not in operation from 2011-2012 for statuary clearance.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Nil	Monthly & Annual Returns has not submitted for last 11 years.	The mine is not in operation from 2011-2012 for statuary clearance.

9c Scrutiny of Nil Annual return on land use pattern for area under pits, reclaimed area, dumps etc.

9d Scrutiny of Nil Annual return on afforestation

9e Scrutiny of Nil Annual return on mineral reject generation (Grade and quantity)

9f Scrutiny of Nil Annual return on ROM stock and/or graded ore

9g Scrutiny of Nil Annual return on sale value, Ex. Mine price and production cost

9h Scrutiny of Nil Annual return on fixed assets

9k Scrutiny of Nil Annual return on mining machineries Monthly & Annual Returns has not submitted for last 11 years.

Monthly & Annual Returns has not submitted for last 11 years.

Monthly & Annual Returns has not submitted for last 11 years.

Monthly & Annual Returns has not submitted for last 11 years.

Monthly & Annual Returns has not submitted for last 11 years. Monthly & Annual Returns has not submitted for

last 11 years. Monthly & Annual Returns has not submitted for last 11 years.

2011-2012 for statuary clearance. The mine is not in operation from 2011-2012 for statuary clearance. The mine is not in operation from 2011-2012 for

The mine is not in

operation from

statuary clearance.

The mine is not in operation from 2011-2012 for statuary clearance.

The mine is not in operation from 2011-2012 for statuary clearance. The mine is not in operation from

2011-2012 for statuary clearance.

The mine is not in operation from 2011-2012 for statuary clearance.

Details of violations observed during current inspection and compliance position of violation pointed out					
Violation observed			Show couse position		
Rule NO.	Issued on	Compliance or	n Rule NO	). Issued on Compliance on	

#### Date :

### (G.SORNADURAI KANNAN)

Indian Bureau of Mines