



भारतसरकार /Govt. of India
खानमंत्रालय/Ministry of Mines
भारतीयखानब्यूरो/ Indian Bureau of Mines
हैदराबादक्षेत्रीयकार्यालय/ Hyderabad Regional Office



Phone No.: (040)-29555603/29554603
E-mail: ro.hyderabad@ibm.gov.in
No. TS/SUPT/LST-66/HYD

Room No.603, 6th Floor,
CGO Towers, Kavadiguda,
Secunderabad – 500 080.
Date:20.07.2023

To

Sri. Chandra Shekhar Pandey, Nominate Owner
My Home Industries Pvt. Ltd.
9th Floor, Block-3,
My Home Hub Madhapur
Hyderabad.

Sub: Violation of provisions of Mineral Conservation and Development Rules,2017 in respect of your My Home Limestone Mine-II (38TEL696001) over an extent of 252.407 ha. situated in Mellacheruvu & Yepalamadhavaram Village, Mellacheruvu Mandal, Suryapet District, Telangana State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during Modification of Mining Plan inspection on 14.07.2023 in the presence of Sri.N.Naresh, Manager& Sri. R. Yadaiah, Geologist.

RuleNo.	Nature of Violation observed
11 (1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</p> <p>Mining operations are not carried out in accordance with the proposals given in approved Modification of Mining Plan vide letter No. AP/NLG/MP/Lst-75 dated 14.07.2017 to the extent indicated below.</p> <p>i. It was proposed to excavate topsoil of 23925 cu.m in the year 2022-23, whereas only 6305.19 cu.m of topsoil excavated in the year 2022-23.</p> <p>ii. It was proposed to produce ROM of 192604.52tonnes in the year 2022-23, whereas only 2799 tonnes production reported in the year 2022-23.</p> <p>iii. It was proposed to plant sapling of 800 Nos. in the year 2022-23, whereas only 474 Nos. of saplings planted during the year 2022-23.</p>

I/13476/2023

34A (1)	<p>Every lessee shall carry out a drone survey of the leased area and upto hundred metres outside the lease boundary in the month of April or May every year and submit the processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the Controller General on or before 1st day of July every year.</p> <p>Digital aerial images of the mining lease area have not been submitted as per the Standard Operating Procedure prescribed by Indian Bureau of Mines. The deviations are as follows:</p> <ol style="list-style-type: none"> 1. Ground control points not clear in the orthomosaic image. 2. Lease boundary is not matching with the boundary pillars in the field. 3. Difference in the shape files w.r.t actual ground features. 3. Approved DGPS co-ordinates not submitted.
---------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 (1) of MCDR. Further, inability to comply the provision of Rule 11(1) is liable for suspension of Mining operations under 11(2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(Madhu Sudhan Yadav. M)
Assistant Controller of Mines

Copy for information:

1. खान नियंत्रक (दक्षिणक्षेत्र), भारतीय खान ब्यूरो, बेंगलोर.
2. The Director, Department of Mines & Geology, Govt. of Telangana, II floor, My Home Sarovar Plaza, Adarsh Nagar, Hyderabad-500063.
3. The Assistant Director, Dept. of Mines & Geology, 1-2-270/87/33/B, Krishna Nagar Colony, Road No.3, Suryapet-508213. Telangana State.

मधु सुधन यादव.एम (Madhu Sudhan Yadav. M)
सहायक खान नियंत्रक/ Assistant Controller of Mines