

Violation Letter / उल्लंघन पत्र

भारत सरकार/GOVERNMENT OF INDIA खान मंत्रालय/MINISTRY OF MINES भारतीय खान ब्यूरो/INDIAN BUREAU OF MINES

Reg. AD/Speed Post/ Email/Fax

क्षेत्रीय खान नियंत्रक कार्यालय/OFFICE OF THE REGIONAL CONTROLLER OF MINES

कमरा नंबर 603, छठवाँ तल, सी0जी0ओ0 टॉवर्स, / Room No. 603, 6th Floor, CGO Towers, कवाडीगुडा, सिकंदराबाद (तेलंगाना)—500080 / Kavadiguda, Secundrabad, (Telangana) - 500080 फोन / Phone: 040–29555603, 29554603, 29553603, ई—मेल / E-mail: ro.hyderabad@ibm.gov.in

File No. AP/KNL/LST-215/Hyd. फाईल क. ए.पी. / कुर्नूल / चू.प.-215 / हैदराबाद प्रति/To,

Shri K. C. Jhanwar,
Deputy Managing Director, CMO,
and Nominated Owner,
M/s UltraTech Cement Limited,
'A' Wing, Auhra Center, 1st Floor,
Mahakali Caves Road,
Andheri (East), Mumbai – 400 093

38 APR 11189 Date: 14/09/2023 38 ए.पी.आर. 11189 दिनांक 14/09/2023

> श्री के. सी. झांवर, डिप्टी मेनेजिग डायरेक्टर, सी.एम.ओ., एवं नामित मालिक, सर्वश्री अल्ट्राटेक सीमेंट लिमिटेड, 'ए' विंग, ऑरा सेंटर, प्रथम तल, महाकाली केव्स रोडं, अंधेरी (पूर्व), मुम्बई — 400 093

বিষয: Violation of provisions of MCDR, 2017 in respect of your Tummlapenta-2 Limestone Mine over an extent of 114.372 Ha. situated in Village Tummalapenta, Mandal Kolimigundla, District Kurnool of Andhra Pradesh State.

महोदय / महोदया,

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in the above mine during the inspection on 23/08/2023 by the undersigned in presence of the mine officials Shri K. Naga Sidda Reddy, Agent (Mines).

Rule	Nature of violation
No.	
Rule	No holder of a mining lease shall commence or carry out mining operations in any area except
11	in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of
(1)	Mines or prepared and certified in accordance with the system established by the State
	Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved
	by the competent authority of the Atomic Minerals Directorate for Exploration and Research,
	in respect of minerals specified in Part B of the First Schedule to the Act where the grade of
	such atomic minerals is equal to or above the threshold value limits declared under Schedule-
	A of the Atomic Minerals Concession Rules, 2016.
	The following deviations have been found in the mine from the approved Modified Mining
	Plan vide letter no. AP/KNL/MP/Lst130/Hyd. Hyderabad dated 26/02/2021 for the period
	of F.Y. 2021-22 to 2025-26.
	Production & Development:
	During F.Y. 2022-23; it was proposed to carry out the production and development in
	between UTM Co-ordinates N1664300 to N1664390 and E181900 to E182010, whereas,
	production and development has been done in between UTM co-ordinates N1664440 to N1664580 and E181850 to E181925.
	N1004380 unu E101030 to E101923.
	Stacking of Mineral/Ore: Certain quantity of the mineral/ore has been kept in between UTM
	Co-ordinates N1664500 to N1665500 and E181500 to E182500 without any approved
	proposal.

Rule	Nature of violation
No.	
Rule	Protective Measures: No protective measures have been taken around the several numbers
11	of old abandoned quarries situated in between UTM co-ordinates N1664000 to N1666000
(1)	and E181000 to E182500.
Rule	Machinery and Plant: (1) Where heavy earth moving machinery is used in mines, the holder
19	of a mining lease shall maintain log books duly authenticated by the manager or mining
(1)	engineer of such mines in respect of each machine showing date-wise account of hours
	worked, hours not worked, reasons for non-working, consumption of fuel or energy and
	lubricants and output of the machine during the corresponding working hours.
	Logbooks of the machineries deployed in the mining operations have not been maintained.

- 02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence, punishable under Rule 62(1) of MCDR, 2017 as well as Fine may be imposed as specified under Schedule-III of rule 62(2) of MCDR, 2017 Amended up to 3rd November 2021.
- 03. The mining operations and dispatches can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय,

(शैवाल कार्तिकेय) वरिष्ठ खनन् भूविज्ञानी भारतीय खान ब्यूरो, हैदराबाद

प्रतिलिपिः सूचनार्थ एवं आवश्यक कार्यवाही हेतु :--

- 1. खान नियंत्रक (दक्षिण), भारतीय खान ब्यूरो, बंगलूर (कर्नाटक) 560022
- The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5th and 6th Floors, BTPS Road, PO Ibrahimpatnam-521456, Vijayawada, Krishna District.
- Shri K. Naga Sidda Reddy, Agent (Mines), M/s UltraTech Cement Limited, Andhra Pradesh Cement Works, Village & Post Bhogasamudram, Mandal Tadipatri, District Anantapur, State Andhra Pradesh, Pin Code 515413.

/ (शैवाल कार्तिकेय) वरिष्ठ खनन् भूविज्ञानी भारतीय खान ब्यूरो, हैदराबाद