MCDR-MiFLOBXT/2/2022-JBP-IBM_RO_JBP

VIOLATION LETTER Email/Registered AD/Speed post

1/14861/2023



Government of India Ministry of Mines Indian Bureau of Mines Office of the Regional Controller of Mines, Jabalpur

Mine Code: - 44MPR35176 Jabalpur, Dated:

Sri Surendra Singh Saluja, Nominated Owner M/s Rakesh Agencies. 26/52, Madhai Ka Bagicha, Alfart Ganj, Katni (M.P.)483501 **Email** gp.garg@anandmining.com

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to **Karigohi Bauxite & Ochre Mine** over an area of **15.62 hect**. in **Satna** District (M.P.) Sir,

The following provisions of the Mineral Conservation and Development Rules 2017 were found violated in your above mine during the inspection on 29/07/2023 by the undersigned, accompanied by Mohammad Kafil, Mining Engineer, Dharmendra Pandey, Geologist and Shri G.P.Garg representative of lessee.

नियम	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule	No holder of a mining lease shall commence or carry out mining operations in any area
34A	except in accordance with the mining plan approved, modified or reviewed by the Indian
	Bureau of Mines or prepared and certified in accordance with the system established by the
	State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or
	approved by the competent authority of the Atomic Minerals Directorate for Exploration and
	Research, in respect of minerals specified in Part B of the First Schedule to the Act where
	the grade of such atomic minerals is equal to or above the threshold value limits declared
	under Schedule-A of the Atomic Minerals Concession Rules, 2016. Read with MCR
	(Amendment),2021notified in Gazette of India vide dated 02/11/2021
	The Review of Mining Plan of above mentioned mine was approved vide letter No
	MP/Satna/Bauxite/RMP-14/2021-22 dated 09/07/2021 incorporating proposal of working
	from 2021-22 to 2022-23. Subsequently next Review of Mining plan was approved on
	22/03/2023 vide letter no. E 2361 MCDR-MPC0BXT/2/2022-JBP-IBM_RO_JBP for the
	proposal period 2023-24 to 2027-28. During the inspection it was found that following
	activities have been carried out with violating the approved proposals: -
	Extraction of mineral from 7.5m statutory barrier zone between BP.No. 3/2 to BP.No3
	have also been carried out in continuation to the site proposed for 2023-24.
	Every lessee, other than those covered under sub-rule (1), shall submit soft copy of high resolution Geo referenced Ortho-rectified Multispectral satellite images of the leased area
	and up to hundred metres outside the lease boundary taken in the month of April to June of
	every year, to the Controller General on or before 1st day of July of the that year in the
	standards formats such as GeoTIFF along with metadata or any other format as may be
	specified by the Indian Bureau of Mines in this regard:
	A soft copy of high resolution Geo referenced Ortho-rectified Multispectral satellite
	images of the leased area and up to hundred metres outside the lease boundary taken
	in the month of April to June has not been submitted and the processed output [digital
	elevation model (DEM) and Orthomosaic] images have not been submitted as specified
	in the rule.
45(7)	If it is found that the holder of a mining lease or the person or company engaged in trading
	or storage or end-use or export of minerals, as the case may be, has submitted incomplete or
	wrong or false information in daily or monthly or annual returns or fails to submit a return
	within the date specified; then,–
	in the case of mining of minerals by the holder of a mining lease, the Regional Controller of
	Mines,
	i. order suspension of all mining operations in the mine and to revoke the order of
	suspension only after ensuring proper compliance;

MCDR-MiFL0BXT/2/2022-JBP-IBM_RO_JBP

1/14861/2023

ii. take action to initiate prosecution under these rules;

iii. recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;

On examination of Annual Return for the year 2022-23 it is observed that data of annual return are incomplete & having following deficiencies: -

- 1. Part I, item no. 9 &10 and part II item no.1

 Name of Mining Engineer and Geologist not furnished in part I whereas in part II strength of Part time Mining Engineer and part time Geologist indicated.
- 2. Part VII Cost of production :-

In calculation of cost of production as a taxes Rs. 0 had taken into account which is not correct.

Necessary changes need be incorporated.

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 3. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 are not found satisfactory. In case Non-compliance of Rule 45(7) of MCDR-2017, Necessary action shall be initiated as deemed fit.
- 4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(Raghubir Sharan Garg) Assistant Controller of Mines For Regional Controller of Mines

Copy to:

- 1- The Director of Geology & Mining, Govt. of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal (M.P.)
- 2- The District Collector, Satna (M.P.) for information & appropriate action.

Assistant Controller of Mines For Regional Controller of Mines

NOO Copy to:_

- 1- Controller of Mines(CZ) for kind information.
- 2- DDG, Mining & Mineral Statistics Division, Indian Bureau of Mines, Nagpur for refer back of Annual Return for the year 2022-23 to rectification as pointed out above under rule 45(7).

Assistant Controller of Mines For Regional Controller of Mines